PUBLIC HEARING BOARD OF HOUSING QUALITY APPEALS CITY HALL McCLOSKEY CONFERENCE ROOM SEPTEMBER 18, 2019 4:00 P.M.

ALL ITEMS ARE ON THE CONSENT AGENDA

I.	ROL	L C	ALL

II. **REVIEW OF SUMMARY** – July 17, 2019, August 21, 2019

III. PETITIONS

- 1) 19-TV-50, **609 E. University Street**, Choice Realty Management (Raymond Kahn). Previously heard July 17, 2019. Request for an extension of time to complete repairs. p. 2
- 2) 19-TV-64, **211 S. Kimble Drive**, JSA Investment. Request for an extension of time to complete repairs. p. 9
- 3) 19-TV-65, **2430 W. 3rd Street**, JSA Investments. Request for an extension of time to complete repairs.
- 4) 19-TV-66, **2663 E. 7th Street**, Michelle Mosier (CRE Rentals). Request for an extension of time to complete repairs.
- 5) 19-TV-68, **857 E. Sherwood Hills Drive**, Christina Divine. Request for an extension of time to complete repairs. p. 69
- 6) 19-TV-69 **2360 S. Henderson Street**, Qiuen Zhu. Request for an extension of time to complete repairs. p. 76
- 7) 19-TV-70, **1900 S. Oakdale Drive**, Doug Cook (ASHH, LLC). Request for an extension of time to complete repairs. p. 82
- 8) 19-AA-71, **213 S. Jefferson Street**, Nicholas Weybright. Request for relief from an administrative decision. p. 90
- 9) 19-AA-72, **3336 S. Oaklawn Circle**, Yiping Lin. Request for relief from an administrative decision. p. 99
- 10) 19-AA-74, **803 N. Lincoln Street**, Isaac Peterson (Tariq Khan). Request for relief from an administrative decision.

IV. GENERAL DISCUSSION

V. PUBLIC COMMENT

VI. ADJOURNMENT

Auxiliary aids for people with disabilities are available upon request with adequate notice. Please call <u>812-349-3429</u> or e-mail <u>human.rights@bloomington.in.gov</u>.



Board of Housing Quality Appeals Staff Report: Petition for Extension of Time

Meeting Date:

September, 18th, 2019

Petition Type:

An extension of time to complete exterior repairs to the siding.

Petition Number:

19-TV-50 (Old Buisness)

Address:

609 East University Street.

Petitioner:

Choice Realty & Management.

Inspector:

Kenny Liford

Staff Report:

April 8th, 2019 Completed Cycle Inspection Report

June 5th, 2019 BHQA application received

August 14th, 2019 2nd BHQA application received.

Owner has requested a 2nd extension of time to complete replacement/repairs to the siding.

Staff recommendation: Grant the request.

Conditions: Have all siding replacement/repairs completed and a re-inspection scheduled by the deadline listed below.

Compliance Deadline: October 5th, 2019 To call and schedule re-inspection for the siding.


Attachments: Cycle report, BHQA Appeal





Application for Appeal To The Board of Housing Quality Appeals P.O. Box 100 Bloomington, IN 47402 812-349-3420 hand@bloomington.in.gov

NOTE: A \$20 filing fee must accompany this application. The property will not be placed on the meeting



BY:

agenda until the filing fee is received.
Property Address: 609 E. University
Property Address: 609 E. University Petitioner's Name: Chine Realty & Management Address: 1715 J. Walnut St.
Address: 1715 J. Walnut St.
an O. t. a. C. T. a. t. 47401
Phone Number: Email Address: dena @ call Choice realty. 10m 812-331-7353 Property Owner's Name: Raymond Kohn
Address: 3-16-6 Nistrihara Shibuga-Ku Tokgo Japan 151-00
City: State: Zip Code:
Phone Number: Email Address: vaymenl. a. Kohn C put. cm
Occupants: 5
 The following conditions must be found in each case in order for the Board to consider the request: That the exception is consistent with the intent and purpose of the housing code and promotes public health, safety and general welfare. That the value of the area about the property to which the exception is to apply will not be adversely affected.
Please check the petition type that you are requesting:
An extension of time to complete repairs (Petition type TV)
☐ A modification or exception to the Residential Rental Unit and Lodging Establishment Inspection Program (Petition type V)
Relief from an administrative decision (Petition type AA)
Rescind a variance (Petition type RV)
OFFICE USE ONLY
Petition Number 19-TV-50 (OLD BUSINESS)

Previously HOVED

KL

SEE REVERSE

Please provide details regarding your request below; you may attach any exhibits or additional comments as you deem necessary and pertinent to your request. Be specific as to what you are requesting, the reason or justification for your request, the amount of time needed to bring the property into compliance, and any modifications and/or alterations you are suggesting.

Signature (required): New Documer Chrie Really + Manglint
Name (please print): Date:

Dena Desson

Signature (required): Name (required): Name (Please print): Date: 8/12/19

You may attend the meeting. If you attend, please note that all petitioners presenting a matter to the Board shall be limited to no more than five minutes to present their case and arguments. Additional time can be granted if deemed appropriate by the Board. Please note that if your property is listed on the consent agenda it is more likely than not that your property will not be individually discussed during the Board's

Regust needed to an additional 30 days

the Sidis replacent to This property.

Justine deadlines of extre und has deleged

Justine deadlines of extre und has deleged

this & contractor has been uncle to get this

this & contractor has been uncle to get this

into sehedele that we are using & have

approved to this julis.



RENTAL INSPECTION INFORMATION

APR 1 2 2019

Kahn, Raymond 3-16-6 Nishihara Shibuya-Ku, Tokyo, JP 151-0066

RE: 609 E University ST

Please find the enclosed Rental Inspection Report which contains pertinent information about the Cycle Inspection that was recently conducted at the above referenced property. The inspector has listed all noted violations and recommendations on the enclosed Rental Inspection Report. You have sixty (60) days from the date of this letter to correct the violations listed on the report.

Once violations have been corrected, it is your responsibility to call the Housing and Neighborhood Development office within this 60 day window but no later than **JUN 1 2019** to schedule a re-inspection. You have the right to appeal any violation of Bloomington Municipal Code Title 16 noted on the rental inspection report to the Board of Housing Quality Appeals.

This report is issued in accordance with BMC 16.10.020 and 16.10.040 of the Residential Rental Unit and Lodging Establishment Inspection Program. Residential Rental Occupancy Permits will not be issued until all interior and exterior violations have been corrected, and all fees have been paid. Bloomington Municipal Code requires that all violations of all Titles of the BMC must be in compliance before a permit will be issued. Please be advised that non-compliance by the deadlines listed in this letter may limit the permit period to a maximum of three (3) years.

If the owner's or agent's contact information has changed since your last inspection, please submit a new registration form to the HAND Department. The registration must be signed by the owner of the property, not the agent. All rental forms and documents can be found at www.bloomington.in.gov/hand. If you do not have access to the internet, you may contact HAND at 812-349-3420 and forms will be provided.

If you have any questions regarding the permit process, please call weekdays between 8:00 a.m. and 5:00 p.m., at (812) 349-3420.

Sincerely, Housing & Neighborhood Development Encl:Inspection Report,

Xc: Choice Realty & Management: 1715 S. Walnut Street, Bloomington, IN 47401

City Hall





CYCLE INSPECTION REPORT

1873

Owner(s)

Kahn, Raymond 3-16-6 Nishihara Shibuya-Ku, Tokyo, JP 151-0066

Agent

Choice Realty & Management 1715 S. Walnut Street Bloomington, IN 47401

Prop. Location: 609 E University ST Number of Units/Structures: 1/1

Units/Bedrooms/Max # of Occupants: Bld 1: 1/5/5

Date Inspected: 04/05/2019 Primary Heat Source: Gas

Property Zoning: RC

Number of Stories: 2

Inspector: Kenny Liford Foundation Type: Basement

Attic Access: Yes

Accessory Structure: None

Monroe County Assessor's records indicate this structure was built in 1925. There were no requirements for emergency egress at the time of construction.

INTERIOR

Entry, Living Room (11-0 x 25-6)

No violations noted.

Kitchen/Dining Room (11-6 x 10-8)

Install a cable clamp where the power supply enters the garbage disposal. BMC 16.04.060(c)

Bathroom/Laundry Room

Secure the cover for the electric panel. BMC 16.04.060(b)

South Bedroom (8-0 x 18-6)

The smoke detector in this room appears to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detector in an approved location. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

City	Ha	١	Ì
------	----	---	---

South Bedroom (Continued)

Provide operating power to the smoke detector. IC 22-11-18-3.5

Existing Egress Window Measurements:

Height: 21 ½ inches Width: 34 ¾ inches Sill Height: 24 inches

Openable Area: 5.18 sq. ft.

Note: These measurements are for reference only. There is no violation of the

emergency egress requirements.

Basement.

No violations noted.

2nd Level

NW Bedroom (7-0 x 11-7), NE Bedroom (9-0 x 12-0)

No violations noted.

Existing Egress Window Measurements:

Height: 24 ½ inches Width: 30 ¼ inches Sill Height: 25 inches Openable Area: 5.14 sq. ft.

Note: These measurements are for reference only. There is no violation of the

emergency egress requirements.

Bathroom

No violations noted.

SE Bedroom/Sitting Room $(8-0 \times 13 + 9-0 \times 12)$

Provide operating power to the smoke detector. IC 22-11-18-3.5

Existing Egress Window Measurements:

Height: 24 ½ inches Width: 30 ¼ inches Sill.Height: 25 inches Openable Area: 5.14 sq. ft.

Note: These measurements are for reference only. There is no violation of the

emergency egress requirements.

SW Bedroom (10-0 x 12-0)

No violations noted.

Existing Egress Window Measurements:

Height: 24 ½ inches Width: 30 ¼ inches Sill Height: 25 inches Openable Area: 5.14 sq. ft.

Note: These measurements are for reference only. There is no violation of the

emergency egress requirements.

EXTERIOR

Properly repair or replace damaged or deteriorated siding in a manner that leaves the structure weather tight. This is to be done in a workmanlike manner and includes but is not limited to all damaged or deteriorating siding and structural members. BMC 16.04.050(a)

OTHER REQUIREMENTS

Furnace Inspection Documentation

Thoroughly clean and service the furnace, inspect and test shut off valves for proper operation. Documentation from a professional HVAC contractor for this service is acceptable and encouraged. Servicing shall include a test for carbon monoxide. Acceptable levels of carbon monoxide are as follows:

Desired level:

0 parts per million (ppm)

Acceptable level in a living space:

9 ppm

Maximum concentration for flue products:

50 ppm

BMC 16.01.060(f), BMC 16.04.060(c), BMC 16.04.060(b)

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.03.030(d): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner and the agent, the occupant load of the unit, the number of bedrooms, the expiration date of the permit, and any variances that have been granted for the property. BMC 16.03.030(c)

This is the end of this report.



Board of Housing Quality Appeals Staff Report: Petition for Extension of Time

Meeting Date:

September 18, 2019

Petition Type:

An extension of time to complete repairs.

Petition Number:

19-TV-64

Address:

211 S. Kimble Dr.

Petitioner:

JSA Investments

Inspector:

Norman Mosier

Staff Report:

April 1, 2019 – Conducted cycle inspection July 16, 2019 – Conducted Re-inspection

July 25, 2019 – Received BHQA Appeal

The Petitioner is requesting an extension of time to complete the repairs in Unit 16 for a window and in Unit 32 for a sliding glass door. Petitioner states that it will take six to eight weeks for the parts to be received from the vendor.

Staff recommendation:

Grant the request.

Conditions:

Complete all repairs and schedule for re-inspection no later than the deadline stated below, or this case will be turned over to the City of Bloomington Legal Department for further action,

including, but not limited to, the possibility of fines.

Compliance Deadline: September 30, 2019 - For all repairs including life safety violations.

Attachments: Cycle Report, Remaining Violations Report, BHQA Appeal, Petitioner's Letter





DECIRAVED Note: 25 2019

Application For Appeal To The By:
Board of Housing Quality Appeals
P.O. Box 100
Bloomington, IN 47402
812-349-3420
hand@bloomington.in.gov

Property Address	3: 211 S. Kimble D	r. Blooming	oton IN 47404	4		Alberta de la constanta de la
Petitioner's Name	e: JSA Investmen	ts	· · · · · · · · · · · · · · · · · · ·			
Address: 1600 A 5	T NE Suite 12	. transaction - 2000-				
City: Linton		State: 1	ndiana	¥	Zip Code: 47441	
Phone Number:	8126994229	E-mail	Address: ma	ndy@rfpmg	.com	
Owner's Name:	Jody Todd		- Total Control Contro	منسفسين معطون ومر	· · · · · · · · · · · · · · · · · · ·	A section of the sect
Address: 1600 AS	T NE Suite 12				,	
City: Linton		State:	Indiana	E	Zip Code: 47441	
Phone Number:	8127987117	E-mail	Address: jod	y@rfpmg.co	m	
Occupants:	T. E. Language	· · · · · · · · · · · · · · · · · · ·		·		
1. That the exception health, safety, at 2. That the value of affected.	ion is consistent nd general welfa of the area abou	with the i tre. t the prop	ntent and pur	the excep	the Board to consider the housing code and prometion is to apply will not b	e adversely
Identify the varia	ance type that	you are re	questing fr	om the fol	lowing drop down men	property.
Variance Type:	An extension of til	ne to comp	olete repairs. (P	etition Type	:TV)	<u> </u>
Reminder: A \$20.00 filing fee Application or the	application wil	not be co	nsidered to b	e	(Will be assigned by BH	QA)
completel A comprior to the meeti placed on that me	pleted application of the properties of the contraction of the contrac	n has to b	ie submitted	1	tion Number: <u>19-7V</u>	-64

In the space provided below please write a brief narrative regarding your request. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property and compliance, as well as any modifications and/or alterations you are suggesting. The following information must be: included dependent upon the type of variance you are requesting:

- A. An extension of time to complete repairs. (Petition type: TV)
 - 1. Specify the items that need the extension of time to complete.
 - 2. Explain why the extension is needed.
 - 3. Specify the time requested.
- B. A modification or exception to the Housing Property Maintenance Code. (Petition type: V)
 - 1. Specify the code reference number you are appealing.
 - 2. Detail why you are requesting the variance.
 - 3. Specify the modifications and or alterations you are suggesting.
- C. Relief from an administration decision. (Petition type: AA)
 - 1. Specify the decision being appealed and the relief you are seeking.
- D. Rescind a variance. (Petition type: RV)

entered will not be saved.

- 1. Detail the existing variance.

Specify the reason the variance is no longer needed.			
Unit 32 is requiring a new sliding glass door. We have Tommy D's contacted, bu and get installed.	t these tak	e 6-8 weeks	to come in
Unit 16 will need a new window. We have Tommy D's contacted but again will to get installed.	ake 6-8 we	eks to come	in and then
·			
		والمراورين والمراكدة المراكدة	
Signature (Required): Deff Down	7		
Name (Print): Jeff Slaven	Date:	7-2	5-2019
Important information regarding this application format: 1. This form is designed to be filled out electronically, printed, then the special mail).	returned,	/submitted	l manually

2. This document may be saved on your computer for future use, however, any data that you have



REMAINING VIOLATION INSPECTION REPORT

JUL 1 7 2019

855

Owner(s)

Jsa Investments 1600 A St Ne Suite 12 Linton, IN 47441

Prop. Location: 211 S Kimble DR Number of Units/Structures: 24/2

Units/Bedrooms/Max # of Occupants: Bld 1: Bld B: 2/1/5 10/2/5, Bld C: 2/1/5 10/2/5

Date Inspected: 04/01/2019 Primary Heat Source: Gas Property Zoning: CA

Number of Stories: 2

Inspector: Norman Mosier Foundation Type: Basement

Attic Access: Yes

Accessory Structure: None

Monroe County Assessor's records indicate this structure was built in 1970. There were no requirements for emergency egress at the time of construction.

One Bedroom

Living Room (17-5 x 10-11) Kitchen (10-1 x 8-9)

Bedroom 10-4 x 10-2)

Bathroom

Two Bedroom

Living Room (17-5 x 10-11)

Kitchen (10-1 x 8-9) Bedroom (10-4 x 10-2) Bedroom (10-4 x 10-2)

Bathroom

Existing Egress Window Measurements:

Height: 34 inches
Width: 16 inches
Sill Height: 49 inches

Openable Area: 3.77 sq. ft.

Height: 31 inches Width: 13 inches Sill Height: 51 inches

Openable Ares: 2.79 sq. ft.

At the time this structure was built, there were no code requirements for emergency egress for a sleeping room. The Housing & Neighborhood Development Department strongly recommends that the sleeping room egress windows be modified or replaced with a larger window to aid in emergency escape. BMC-16.04.400 (b)

Neighborhood Division (812) 349-3421

REINSPECTION REQUIRED

This report is your final notice from the Housing and Neighborhood Development Office that this rental property continues to be in violation of the Residential Rental Unit and Lodging Establishment Inspection Program of Bloomington.

If you have made all of the repairs on this report, contact our office immediately to schedule the required re-inspection.

Failure to make repairs or to schedule the required re-inspection will result in this matter being referred to the City Legal Department. Legal action may be initiated against you under BMC 16.10.040

It is your responsibility to contact the Housing and Neighborhood Development Office to schedule the required re-inspection. Our mailing address and telephone number are listed below.

INTERIOR

Building B

Unit 15

Hallway

Repair or replace door knob/lock assembly (Closet door) in a manner so that it functions as intended. BMC 16.04.060(a)



Replace the missing smoke detector. IC22-11-18-3.5

Right Bedroom

Repair the hole in the wall. BMC 16.04.060(a)



Install the missing electrical service panel. BMC 16.04.060 (b)



Install the hanging electrical receptacle on the north wall. BMC 16.04.060 (b)

Interior walls shall be free of holes, cracks, peeling paint and/or deteriorated drywall/plaster, north wall. BMC 16.04.060(a)

Unit 17

Bathroom

Secure toilet to its mountings. BMC 16.04.060(c)



Replace non-functioning or incorrectly wired GFCI receptacle(s), (Wont trip) per Indiana Electric Code requirements. BMC 16.04.020 (IEC 210.8) and BMC 16.04.060(b)

Kitchen_

Repair the surface of the ceiling to be free of holes, cracks, peeling paint and/or sagging materials. BMC 16.04.060(a)

Unit 23

Kitchen

Repair or replace closet doors so they function as intended. BMC 16.04.060(a)

BUILDING C

Unit 14

Hallway

Replace the missing protective cover for the light fixture. BMC 16.04.060(c)

Hall Bath

Secure the loose sink to the wall. BMC 16.04.060 (a)

Finish the drywall repair, sand and paint. BMC 16.04.060 (a)

Replace the damaged door, and to fit the door jamb and latch properly. BMC 16.04.060 (a)

Unit 22

Hall Bath

Secure the loose toilet to its mountings. BMC 16.04.060 (c)

Repair the toilet to eliminate unnecessary water use. BMC 16.04.060(a)

Unit 24

Kitchen

Install a cable clamp where the power supply enters the garbage disposal. BMC 16.04.060(c)

Repair/replace the broken oven door, door comes apart when opened. BMC 16.04.060 (a)

Hall Bath

Repair the surface of the ceiling to be free of holes, cracks, peeling paint and/or sagging materials. BMC 16.04.060(a)

Properly secure the loose and hanging GFCI receptacle into the receptacle box. BMC 16.04.060 (b)

Unit 32

Living Room

Replace the missing smoke detector. IC22-11-18-3.5

Repair the sliding glass door to open easily. BMC 16.04.060 (b)

Replace damaged screen on sliding glass screen door. BMC 16.04.060 (a)

Repair the surface of the ceiling to be free of holes, cracks, peeling paint and/or sagging materials, at south wall. BMC 16.04.060(a)

Furnace Closet

Maintain minimum clearances from combustibles:

- Fuel-fired appliances:
- Single-wall vent connectors:
- 36" clearance from combustible storage
- 1" clearance from Flow Guard Gold CPVC 6" clearance for other combustibles
- Double-wall vent connectors:
- Draft hood:

1" clearance for all combustibles 6" clearance for all combustibles

BMC 16.04.060(c)

Unit 34

Furnace Closet

Documentation for furnace not submitted, see other requirements.

R Bedroom

Repair the door to latch properly. BMC 16.04.060 (a)

Unit 16

Living Room

Every window shall be capable of being easily opened and held in position by its own hardware, dirt in track. BMC 16.04.060(b)

Kitchen

Repair garbage disposal to function as intended, jammed. BMC 16.04.060(c)

Unit 26

R Bedroom

Repair the door to latch properly. BMC 16.04.060 (a)

OTHER REQUIREMENTS

Furnace Inspection Documentation for UNIT 34

Thoroughly clean and service the furnace, inspect and test shut off valves for proper operation. Documentation from a professional HVAC contractor for this service is acceptable and encouraged. Servicing shall include a test for carbon monoxide. Acceptable levels of carbon monoxide are as follows:

Desired level:

0 parts per million (ppm)

Acceptable level in a living space:

9 ppm

Maximum concentration for flue products:

50 ppm

BMC 16.01.060(f), BMC 16.04.060(c), BMC 16.04.060(b)

Registration Form

Complete the enclosed registration form. A street address is required for both owner and agent. This form must be signed by the owner and list all properties owned. If this form is not provided to the HAND department by the compliance deadline and the matter is referred to the Legal Department a fine of \$25 will be assessed. BMC 16.03.020, BMC 16.10.030(b)

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.03.030(d): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner and the agent, the occupant load of the unit, the number of bedrooms, the expiration date of the permit, and any variances that have been granted for the property. BMC 16.03.030(c)

This is the end of this report.



RENTAL INSPECTION INFORMATION

APR 1 0 2019

Jason M Hollar P.O. Box 1122 St. Charles, IL 60174

RE: 211 S Kimble DR

Please find the enclosed Rental Inspection Report which contains pertinent information about the Cycle Inspection that was recently conducted at the above referenced property. The inspector has listed all noted violations and recommendations on the enclosed Rental Inspection Report. You have sixty (60) days from the date of this letter to correct the violations listed on the report.

Once violations have been corrected, it is your responsibility to call the Housing and Neighborhood Development office within this 60 day window but no later than **JUN 0 9 2019** to schedule a re-inspection. You have the right to appeal any violation of Bloomington Municipal Code Title 16 noted on the rental inspection report to the Board of Housing Quality Appeals.

This report is issued in accordance with BMC 16.10.020 and 16.10.040 of the Residential Rental Unit and Lodging Establishment Inspection Program. Residential Rental Occupancy Permits will not be issued until all interior and exterior violations have been corrected, and all fees have been paid. Bloomington Municipal Code requires that all violations of all Titles of the BMC must be in compliance before a permit will be issued. Please be advised that non-compliance by the deadlines listed in this letter may limit the permit period to a maximum of three (3) years.

If the owner's or agent's contact information has changed since your last inspection, please submit a new registration form to the HAND Department. The registration must be signed by the owner of the property, not the agent. All rental forms and documents can be found at www.bloomington.in.gov/hand. If you do not have access to the internet, you may contact HAND at 812-349-3420 and forms will be provided.

If you have any questions regarding the permit process, please call weekdays between 8:00 a.m. and 5:00 p.m., at (812) 349-3420.

Sincerely,
Housing & Neighborhood Development
Encl:Inspection Report,
Xc:Vicky Holdeman: Po Box 1745, Bloomington, IN 47402



CYCLE INSPECTION REPORT

855

Owner(s)

Jason M Hollar P.O. Box 1122

St. Charles, IL 60174

Agent

Vicky Holdeman

PO Box 1745

Bloomington, IN 47402

Prop. Location: 211 S Kimble DR Number of Units/Structures: 24/2

Units/Bedrooms/Max # of Occupants: Bld 1: Bld B: 2/1/5 10/2/5, Bld C: 2/1/5 10/2/5

Date Inspected: 04/01/2019 Primary Heat Source: Gas

Property Zoning: CA Number of Stories: 2 Inspector: Kenny Liford

Foundation Type: Basement

Attic Access: Yes

Accessory Structure: None

Monroe County Assessor's records indicate this structure was built in 1970. There were no requirements for emergency egress at the time of construction.

One Bedroom

Two Bedroom

Living Room (17-5 x 10-11)

Kitchen (10-1 x 8-9) Bedroom 10-4 x 10-2)

Bathroom

Living Room (17-5 x 10-11)

Kitchen (10-1 x 8-9) Bedroom (10-4 x 10-2) Bedroom (10-4 x 10-2)

1-41----

Openable Ares:

Bathroom

Existing Egress Window Measurements:

Height:

34 inches

Height:

31 inches

Width:

16 inches 49 inches Width:

13 inches

Sill Height: 49 Openable Area:

3.77 sq. ft.

Sill Height: 51 inches

2.79 sq. ft.

Note: These measurements are for reference only. There is no violation of the emergency egress requirements.

At the time this structure was built, there were no code requirements for emergency egress for a sleeping room. The Housing & Neighborhood Development Department strongly recommends that the sleeping room egress windows be modified or replaced with a larger window to aid in emergency escape. BMC-16.04.400 (b)

INTERIOR

Building B

Furnace/storage closet

No violations noted.

Unit 15

Repair or replace door knob/lock assembly (Closet door) in a manner so that it functions as intended. BMC 16.04.060(a)

Replace the missing smoke detector. IC22-11-18-3.5

Repair the hole in the wall. BMC 16.04.060(a)

Left Bedroom MISSING ELECT. CERV. PANEL COVER, HOLE-N.WALL, RECEP N. WALL-HANGING This room was not accessible at the time of this inspection. This room must be brought into compliance

with-in the same 60 day deadline as the remainder of this property. This applies even if the tenants do not have access to this area of the property. BMC 16.03.040

Unit 17

Bathroom

/Secure toilet to its mountings. BMC 16.04.060(c)

(Replace non-functioning or incorrectly wired GFCI receptacle(s), (Wont trip) per Indiana Electric Code fequirements. BMC 16.04.020 (IEC 210.8) and BMC 16.04.060(b)

Repair the surface of the ceiling to be free of holes, cracks, peeling paint and/or sagging materials. BMC 46.04,060(a)

Unit 25

Secure all loose electrical receptacles in this room. BMC 16.04.060(b)

Install a temperature/pressure relief (TPR) valve discharge tube on the water heater.

TPR valve discharge tubes:

- shall not be reduced in size from the valve outlet
- shall be rigid galvanized, rigid copper, or any CPVC pipe
- shall not have a threaded discharge end
- drain by gravity
- shall have a minimum 1" air gap where discharging into a sanitary drain, or an approved air
- shall extend to within 6" of floor. BMC 16.04.060(c)

Left Bedroom MISSING SERV. PAVEL COVER

This room was not accessible at the time of this inspection. This room must be brought into compliance with-in the same 60 day deadline as the remainder of this property. This applies even if the tenants do not have access to this area of the property. BMC 16.03.040





No violations noted.

Unit 37

Hallway

Install approved transition strips along the edge of floor covering in a manner that reduces trip hazards. BMC 16.04.060(a)

Bathroom

Clean and service the exhaust fan so that it functions as intended. BMC 16.04.060(c)

Right Bedroom

Replace broken/missing outlet cover plate. BMC 16.04.060(b)

Unit 35

Living Room

Repair or replace door knob/lock assembly to sliding door in a manner so that it functions as intended. BMC 16.04.060(a)

Hallway

Provide operating power to the smoke detector. IC 22-11-18-3.5

Common Laundry

No violations noted.

Unit 11

Kitchen

This room (Furnace Closet) was not accessible at the time of this inspection. This room must be brought into compliance with-in the same 60 day deadline as the remainder of this property. This applies even if the tenants do not have access to this area of the property. BMC 16.03.040

ί

Bathroom

Seal the base of shower surround at the top of the tub. BMC 16.04.060(a)

Unit 13

Bathroom

Scal edge of floor covering adjacent to bathtub. BMC 16.04.060(a)

Unit 23

Living Room

Replace broken/missing outlet cover plate. BMC 16.04.060(b)

Interior walls (Entry to Kitchen) shall be free of holes, cracks, peeling paint and/or deteriorated drywall/plaster. BMC 16.04.060(a)

Kitchen

Repair or replace closet doors so they function as intended. BMC 16.04.060(a)

Replace the missing smoke detector. IC22-11-18-3.5

Unit 23 (Continued)

Bathroom

Secure toilet to its mountings. BMC 16.04.060(c)

The water supply system shall be installed and maintained to provide a supply of water to plumbing fixtures, devices and appurtenances in sufficient volume and at pressures adequate to enable the fixtures to function properly, safely, and free from defects and leaks (repair faucet in a manner so that there is adequate water pressure and volume). BMC 16.04.060(c)

Repair the sink drain to function as intended. BMC 16.04.060(c)

Left Bedroom

Replace the damaged or missing trim around window. BMC 16.04.060(a)

Unit 21

Bathroom

Secure toilet to its mountings, BMC 16.04.060(c)

Unit 33

Right Bedroom

Repair the window to be weather tight. The sashes shall fit snugly and properly within the frame. Replace any missing or deteriorated glazing compound. Windows shall be easily and fully openable and shall remain fully open using hardware that is part of the window. BMC 16.04.060(b)

Living Room

Repair the sliding door to open and close easily. And latch as intended. BMC 16.04.060(b)

Unit 31

No violations noted.

Building C

Common Hallway

2ND level

Loose handrail at second level, BMC 16.04.060 (b)

3rd level

Repair or replace existing smoke detector in a manner so that it functions as intended.

IC 22-11-18-3.5

Replace the missing register vent in the ceiling on the right side of ceiling, and secure the loose and hanging register vent on left side of ceiling. BMC 16.04.060 (a)

Unit 12

L Bedroom

Secure the loose hinges on the door. BMC 16.04.060 (a)

Unit 14

Living Room

Secure the loose receptacle east wall. BMC 16.04.060 (b)

Hallway

Replace the missing protective cover for the light fixture. BMC 16.04.060(c)



Hall Bath

Secure the loose sink to the wall. BMC 16.04.060 (a)

Finish the drywall repair, sand and paint. BMC 16.04.060 (a)

NV Replace the damaged door. BMC 16.04.060 (a) アバ びぬけ

Rearrange furniture in a manner that does not block or hinder access to emergency egress window. BMC 16.04.020(a)(3), 2014 IFC 1003.6, 1030

Unit 22

Repair the sliding glass door screen to function as intended, off track. BMC 16.04.060 (a)

Repair the faucet sprayer on the sink to function as intended by the manufacturer, or remove and properly terminate the line for the sprayer. BMC 16.04.060(c)

Hall Bath

Secure the loose toilet to its mountings. BMC 16.04.060 (c)

Repair the toilet to eliminate unnecessary water use. BMC 16.04.060(a)

Unit 24

Kitchen

Install a cable clamp where the power supply enters the garbage disposal. BMC 16.04.060(c)

Repair/replace the broken oven door, door comes apart when opened. BMC 16.04.060 (a)

Replace the missing smoke detector. IC22-11-18-3.5

Hall Bath

Repair the surface of the ceiling to be free of holes, cracks, peeling paint and/or sagging materials. BMC 16.04.060(a) CFU HANGING OUT OF WALL

Repair the broken window. BMC 16.04.060(a)

Every window shall be capable of being easily opened and held in position by its own hardware. BMC 16.04.060(b)

Unit 32

Living Room

Replace the missing smoke detector. IC22-11-18-3.5

Repair the sliding glass door to open easily. BMC 16.04.060 (b)

Replace damaged screen on sliding glass screen door. BMC 16.04.060 (a)

Repair the surface of the ceiling to be free of holes, cracks, peeling paint and/or sagging materials, at south wall. BMC 16.04.060(a)

Kitchen

Repair/replace the defective garbage disposal. BMC 16.04.060 (c)

Furnace Closet

Maintain minimum clearances from combustibles:

 $\mathbb{N}^{\mathbb{C}}$

Fuel-fired appliances:

• Single-wall vent connectors:

Double-wall vent connectors:

• Draft hood:

BMC 16.04.060(c)

36" clearance from combustible storage

1" clearance from Flow Guard Gold CPVC 6" clearance for other combustibles

1" clearance for all combustibles

6" clearance for all combustibles

Hall Bath

Secure the loose sink to the wall. BMC 16.04.060 (a)

Secure the loose sink faucet. BMC 16.04.060 (c)

L Bedroom

Secure the loose receptacle on the north wall. BMC 16.04.060 (b)

R Bedroom

Repair the hole in wall behind the door. BMC 16.04.060 (a)

Unit 34

Living Room

Replace the broken door handle on the sliding glass door. BMC 16.04.060 (a)

Kitchen

Replace the defective gfci receptacles to the right and left of sink. BMC 16.04.060 (b)

Furnace Closet

Repair the bi fold doors to function as intended. BMC 16.04.060 (a)

Hallway

The smoke detector in this room appears to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detector in an approved location. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

R Bedroom

Repair the door to latch properly. BMC 16.04.060 (a)

Unit 16

Living Room

Every window shall be capable of being easily opened and held in position by its own hardware, dirt in track. BMC 16.04.060(b)

Kitchen

Repair garbage disposal to function as intended, jammed. BMC 16.04.060(c)

Hall Bath
Replace the defective GFCI receptacle to function as intended, won't trip. BMC 16.04.060 (b)

L Bedroom
Secure the loose receptacle on the south wall. BMC 16.04.060 (b)

Repair the door to latch properly. BMC 16.04.060 (a)

<u>Unit 18</u>

Kitchen

Replace the defective GFCI to the right of sink won't trip. BMC 16.04.060 (b)

Hallway
Replace the missing smoke detector. IC22-11-18-3.5

Hall Bath

Repair the surface of the ceiling to be free of holes, cracks, peeling paint and/or sagging materials. BMC 16.04.060(a)

<u>Unit 26</u>

Living Room

Repair the sliding glass door to open easily and lock. BMC 16.04.060 (b)

<u>Kitchen</u>
Secure the lose sprayer to its base. BMC 16.04.060(c)

Replace the defective GFCI receptacle, growls when tripped. BMC 16.04.060 (b)

L Bedroom
Repair the door to latch properly. BMC 16.04.060 (a)

R Bedroom

Repair the door to latch properly. BMC 16.04.060 (a)

Rearrange furniture in a manner that does not block or hinder access to emergency egress window. BMC 16.04.020(a)(3), 2014 IFC 1003.6, 1030

Unit 28

Kitchen

Replace the defective gfci to the left of sink. BMC 16.04.060 (b)

Unit 38

Furnace Closet

Install a temperature/pressure relief (TPR) valve discharge tube on the water heater.

TPR valve discharge tubes:

- shall not be reduced in size from the valve outlet
- shall be rigid galvanized, rigid copper, or any CPVC pipe
- shall not have a threaded discharge end
- drain by gravity
- shall have a minimum 1" air gap where discharging into a sanitary drain, or an approved air break
- shall extend to within 6" of floor. BMC 16.04.060(c)

Unit 38 (Continued)

Kitchen

Repair the faucet sprayer on the sink to function as intended by the manufacturer, or remove and properly terminate the line for the sprayer. BMC 16.04.060(c)

Unit 36

Hallway

Replace the missing smoke detector. IC22-11-18-3.5

EXTERIOR

No violations noted.

OTHER REQUIREMENTS

Furnace Inspection Documentation

Thoroughly clean and service the furnace, inspect and test shut off valves for proper operation. Documentation from a professional HVAC contractor for this service is acceptable and encouraged. Servicing shall include a test for carbon monoxide. Acceptable levels of carbon monoxide are as follows:

Desired level:

0 parts per million (ppm)

Acceptable level in a living space:

9 ppm

Maximum concentration for flue products:

50 ppm

BMC 16.01.060(f), BMC 16.04.060(c), BMC 16.04.060(b)

Tenants and Owners Rights and Responsibilities Summary

A completed copy of the Tenants and Owners Rights and Responsibilities Summary must be provided to this office within 60 days of the date of the inspection or a \$25.00 fine will be levied. BMC 16.03.060(c) and BMC 16.10.030(b)

Inventory Damage List

The owner or his agent shall contact the tenant and arrange a joint inspection of the premises to occur within ten days of the tenant's occupancy of the rental unit. The owner or his agent and the tenant shall at that time jointly complete an inventory and damage list, and this shall be signed by all parties to the tenancy agreement. Duplicate copies of the inventory and damage list shall be retained by all parties and shall be deemed a part of the tenancy agreement. A completed copy of the Inventory & Damage List must be provided to the office within 60 days of the date of the inspection or a \$25.00 fine will be levied. BMC 16.03.050(e) and BMC 16.10.030(b)

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.03.030(d): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner and the agent, the occupant load of the unit, the number of bedrooms, the expiration date of the permit, and any variances that have been granted for the property. BMC 16.03.030(c)

This is the end of this report.



Board of Housing Quality Appeals Staff Report: Petition for Extension of Time

Meeting Date:

September 18, 2019

Petition Type:

An extension of time to complete repairs.

Petition Number:

19-TV-65

Address:

2430 W. 3rd St.

Petitioner:

JSA Investments

Inspector:

Norman Mosier

Staff Report:

April 2, 2019 - Conducted Cycle Inspection

July 11, 2019 – Conducted Re-inspection July 25, 2019 – Received BHQA Appeal

Petitioner is requesting an extension of time to complete the repairs. Agent is in process of hiring contractors (Plumbing and Tree Service) to complete the repairs.

Staff recommendation:

Grant the request.

Conditions:

Complete all repairs and schedule for re-inspection no later than the deadline stated below, or this case will be turned over to the City of Bloomington Legal Department for further action,

including, but not limited to, the possibility of fines.

Compliance Deadline:

October 18, 2019 – For all repairs.

Attachments:

Cycle Report, Remaining Violations Report, BHQA Appeal,

Petitioner's Letter







Application For Appeal BY: To The Board of Housing Quality Appeals P.O. Box 100 Bloomington, IN 47402 812-349-3420 hand@bloomington.in.gov

Property Address	2430 W. 3rd St.	Bloomington IN		
Petitioner's Name	2: JSA investmer	nts		
Address: 1600 A S	T NE Suite 12	and the state of t	- 1504.5cm	
City: Linton	I date up. Timester.	State: Indiana		Zip Code: 47441
Phone Number:	8126994229	E-mail Address	: mandy@rfpmg.c	om
Owner's Name:	lody Todd	1914 Special and appearance of the Assessment		13383
Address: 1600 AS	TNE Suite 12			
City: Linton		State: Indiana		Zip Code: 47441
Phone Number:	8127987117	E-mail Address	i jody@rfpmg.com	
Ŏccupants:				
.That the exception health, safety, and the value of affected.	on is consistent ad general welfa f the area abou	with the intent and tre. t the property to w	d purpose of the l	ne Board to consider the request; housing code and promotes public on is to apply will not be adversely
dentify the varia	nce type that	you are requestin	g from the follo	wing drop down menu:
Variance Type: A	n extension of tir	ne to complete repai	rs. (Petition Type: T	V)
Application or the	application will	ited with the Appea not be considered	to be	(Will be assigned by BHQA)
complete! A comp prior to the meetil placed on that mo	ng application c	on has to be submit leadline in order to	be Petitio	n Number: <u>19 - TV-65</u>

In the space provided below please write a brief narrative regarding your request. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting. The following information must be included dependent upon the type of variance you are requesting:

- A. An extension of time to complete repairs. (Petition type: TV)
 - 1. Specify the items that need the extension of time to complete.
 - 2. Explain why the extension is needed.
 - 3. Specify the time requested.
- B. A modification or exception to the Housing Property Maintenance Code. (Petition type: V)
 - 1. Specify the code reference number you are appealing.
 - 2. Detail why you are requesting the variance.
 - 3. Specify the modifications and or alterations you are suggesting.
- C. Relief from an administration decision. (Petition type: AA)
 - 1. Specify the decision being appealed and the relief you are seeking.
- D. Rescind a variance. (Petition type: RV)
 - 1. Detail the existing variance.

	reason the variance is r			-
Building A Unit 13-Needs a cer material. We are in the proces	tified plumber to come s of finding one to com	in and address le e and look at the	ak above the tub in order to issue.	fix the sagging
Exterior-Tree service has been take these trees down.				schedule to
- Cost iron.	is created.	Cheeds	6.8 mpre w	eeb
	•		_	
				•
	•			
	,			
			•	
Signature (Required):				
Name (Print):			Date:	
Important information re	garding this applica	tion format:	ad they returned/submi	ttad manually

1. This form is designed to be filled out electronically, printed, then returned/submitted manually (e.g. postal mail).

2. This document may be saved on your computer for future use, however, any data that you have entered will not be saved.

Print Form



REMAINING VIOLATION INSPECTION REPORT

JUL 1 7 2019

3029

Owner(s)

Jsa Investments 1600 A St Ne Suite 12 Linton, IN 47441

Prop. Location: 2430 W 3rd ST Number of Units/Structures: 12/1

Units/Bedrooms/Max # of Occupants: Bld 1: 12/2/5

Date Inspected: 04/02/2019 Primary Heat Source: Gas

Number of Stories: 2

Property Zoning: CA

Inspector: Norman Mosier Foundation Type: Basement

Attic Access: Yes

Accessory Structure: None

Monroe County Assessors records indicate this structure was built in 1968. There are no minimum requirements for emergency egress at the time of construction.

Typical Unit:

17-6 x 10-0 Living Room 10-3 x 10-0 Kitchen Bedroom One 10-4 x 10-2 Bedroom Two 10-4 x 10-2 Bathroom

Existing Egress Window Measurements:

Bedroom One: Height: 33.50 inches Width: 12.75 inches Sill Height: 46 inches Openable Area: 2.96 inches Bedroom Two: Height: 33.50 inches Width: 16 inches Sill Height: 46 inches

Openable Area: 3.72 inches

At the time this structure was built, there were no code requirements for emergency egress for a sleeping room. The Housing & Neighborhood Development Department strongly recommends that the sleeping room egress windows be modified or replaced with a larger window to aid in emergency escape.

City Hall

401 N Morton St

Bloomington, IN 47404

REINSPECTION REQUIRED

This report is your final notice from the Housing and Neighborhood Development Office that this rental property continues to be in violation of the Residential Rental Unit and Lodging Establishment Inspection Program of Bloomington.

If you have made all of the repairs on this report, contact our office immediately to schedule the required re-inspection.

Failure to make repairs or to schedule the required re-inspection will result in this matter being referred to the City Legal Department. Legal action may be initiated against you under BMC 16.10.040

It is your responsibility to contact the Housing and Neighborhood Development Office to schedule the required re-inspection. Our mailing address and telephone number are listed below.

INTERIOR:

Building A

Unit 13

L Bedroom:

Rearrange furniture in a manner that does not block or hinder access to emergency egress window. BMC 16.04.020(a)(3), 2014 IFC 1003.6, 1030

Unit 14

Hall Bath:

Secure the loose toilet to its mountings. BMC 16.04.060 (c)

Interior walls shall be free of holes, cracks, peeling paint and/or deteriorated drywall/plaster, above the tub. BMC 16.04.060(a)

Repair the surface of the ceiling to be free of holes, cracks, peeling paint and/or sagging materials, above the tub. BMC 16.04.060(a)

Unit 34

Kitchen:

Repair the left front burner to light as intended. BMC 16.04.060 (c)

Repair the torn linoleum at the kitchen door. BMC 16.04.060 (a)

EXTERIOR:

Trim all tree branches away from the siding and roofline to maintain a 3' clearance, NW corner of structure.

BMC 16.04.040(e)

Seal around all of the windows in this complex to be weather tight. BMC 16.04.050(a)

Re-install all of the improperly installed A/C vents on the 3rd level. BMC 16.04.050(a)

OTHER REQUIREMENTS

Registration Form

Complete the enclosed registration form. A street address is required for both owner and agent. This form must be signed by the owner. If this form is not provided to the HAND department by the compliance deadline and the matter is referred to the Legal Department a fine of \$25 will be assessed. BMC 16.03.020, BMC 16.10.030(b)

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.03.030(d): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner and the agent, the occupant load of the unit, the number of bedrooms, the expiration date of the permit, and any variances that have been granted for the property. BMC 16.03.030(c)

This is the end of this report.



CYCLE INSPECTION REPORT

3029

Owner(s)

Jsa Investments 1600 A St Ne Suite 12 Linton, IN 47441

Prop. Location: 2430 W 3rd ST Number of Units/Structures: 12/1

Units/Bedrooms/Max # of Occupants: Bld 1: 12/2/5

Date Inspected: 04/02/2019

Primary Heat Source: Gas Property Zoning: CA

Number of Stories: 2

Inspector: Norman Mosier Foundation Type: Basement

Attic Access: Yes

Accessory Structure: None

Monroe County Assessors records indicate this structure was built in 1968.

There are no minimum requirements for emergency egress at the time of construction.

Typical Unit:

Living Room	17-6 x 10-0
Kitchen	10-3 x 10-0
Bedroom One	10-4 x 10-2
Bedroom Two	10-4 x 10-2
** .*	

Bathroom

Existing Egress Window Measurements:

Bedroom Two: Bedroom One: Height: 33.50 inches Height: 33.50 inches Width: 16 inches Width: 12.75 inches Sill Height: 46 inches Openable Area: 2.96 inches

Sill Height: 46 inches Openable Area: 3.72 inches

At the time this structure was built, there were no code requirements for emergency egress for a sleeping room. The Housing & Neighborhood Development Department strongly recommends that the sleeping room egress windows be modified or replaced with a larger window to aid in emergency escape.

GENERAL VIOLATION: Gas furnaces, see other requirements.

City Hall Email: hand@bloomington.in.gov Neighborhood Division (812) 349-3421

401 N Morton St https://bloomington.in.gov/haud Housing Division (812) 349-3401

Bloomington, IN 47404 Rental Inspection (812) 349-3420

INTERIOR:

C	Unit 11 Living Room: Secure the loose receptacle on the east wall. BMC 16.04.060 (b)
\subset	<u>Kitchen:</u> Restore power to the GFCI receptacle to the right of the sink. BMC 16.04.060 (a)
	Also secure the same GFCI receptacle, loose. BMC 16.04.060 (b)
	Properly install or replace the aerator on the sink faucet so that it functions as intended. BMC 16.04.060(c)
	<u>Furnace Closet:</u> See other requirements. No violations noted.
\hat{C}	Hallway: Replace the missing smoke detector. IC22-11-18-3.5
ゝ	Hall Bath Repair/replace the loose tiles in the tub, south wall. BMC 16.04.060 (a)
C	Remove the old caulk and install new caulk between the wall and sink. BMC 16.04.060 (a)
~ <i>→</i>	L Bedroom: Replace the missing doorknob. BMC 16.04.060 (a)
/)	R Bedroom: Secure the loose receptacle box on the south wall. BMC 16.04.060 (b)
	Unit 13 Living Room: No violations noted.
	Kitchen: Secure the loose sink faucet handle. BMC 16.04.060(a)
C	Properly install or replace the aerator on the sink faucet so that it functions as intended. BMC 16.04.060(c)
C	Provide a complete directory of all service panels and circuits. BMC 16.04.020(a) IEC 408.4
	Furnace Closet: See other requirements. No violations noted.
C	Hallway: Replace the missing smoke detector. IC22-11-18-3.5
<u> </u>	Hall Bath: Replace the defective GFCI receptacle, BMC 16.04.060 (b)

	Secure the loose toilet to its mountings. BMC 16.04.060 (c)
	R Bedroom: No violations noted.
C.	L Bedroom: Replace the damaged door. BMC 16.04.060 (a)
C	Replace the missing door stop trim. BMC 16.04.060 (a)
Č	Restore power to the receptacle on the east wall. BMC 16.04.060 (a)
1/0	Rearrange furniture in a manner that does not block or hinder access to emergency egress window. BMC 16.04.020(a)(3), 2014 IFC 1003.6, 1030
B C	Unit 23 Living Room: Replace the broken sliding glass screen door. BMC 16.04.060 (a)
, C	Repair the sliding glass door to lock as intended. BMC 16.04.060 (b)
C	Secure the loose receptacle box on the east wall adjacent to the sliding glass door. BMC 16.04.060 (b)
	Kitchen, Furnace Closet, Hallway: No violations noted.
C	Hall Bath: Repair the surface of the ceiling to be free of holes, cracks, peeling paint and/or sagging materials. BMC 16.04.060(a)
C	Interior walls shall be free of holes, cracks, peeling paint and/or deteriorated drywall/plaster, east wall. BMC 16.04.060(a)
<u> </u>	Repair/replace the damaged door. BMC 16.04.060 (a)
Č	Repair the north window to lock as intended. BMC 16.04.060 (b)
	Secure the loose receptacle on the east wall. BMC 16.04.060 (b)
C	<u>L Bedroom:</u> Secure the loose striker plate and repair the door to latch properly. BMC 16.04.060 (a)
	Unit 21 Living Room: No violations noted.
C	Kitchen: Repair the left side burners to light as intended. BMC 16.04.060 (c)
	Furnace Closet: see other requirements. No violations noted.
	4

C	Hallway: Install/replace batteries in smoke detectors so that they function as intended. IC 22-11-18-3.5
C	Replace the missing protective cover for the light fixture. BMC 16.04.060(c)
^	Hall Bath: Secure the loose GFCI receptacle. BMC 16.04.060 (b)
	L Bedroom, R Bedroom: No violations noted.
C	Unit 33 Living Room: No violations noted. Kitchen: Secure the loose sprayer to its base. BMC 16.04.060 (c)
C	Repair the wiring splice under the sink to be inside an approved junction box. BMC 16.04.060(b) (b)
	Furnace Closet: see other requirements. No violations noted.
	Hallway: No violations noted.
\mathcal{C}	Hall Bath: Repair the door to latch properly. BMC 16.04.060 (a)
	Secure the loose sink to the wall. BMC 16.04.060 (c)
C	Secure the loose toilet to its mountings. BMC 16.04.060 (c)
(Re-attach the tub faucet handle. BMC 16.04.060 (c)
$\tilde{\zeta}$	Secure the loose waste and overflow cover plate. BMC 16.04.060 (c)
AC.	Repair the north window to lack as intended. BMC 16.04.060 (b)
C	L Bedroom: Repair the door to latch properly, BMC 16.04.060 (a)
C	Secure the loose receptacle on the north wall. BMC 16.04.060 (b)
Č	Repair the north window to lock as intended. BMC 16.04.060 (b)
_	Unit 31 Living Room: No violations noted.
_	Kitchen:



Install a cable clamp where the power supply enters the garbage disposal. BMC 16.04.060(c)

	No violations noted.
<u>C</u>	Hallway: Replace the missing smoke detector. IC22-11-18-3.5
	Hall Bath: No violations noted.
	L Bedroom, R Bedroom: No violations noted.
M/C	Unit 12 Living Room: Secure the loose receptacle on the south wall. BMC 16.04.060 (b)
	Replace the broken window, east wall, south window. BMC 16.04.060 (a)
\mathbb{C}	Kitchen: Replace the defective sprayer. BMC 16.04.060 (c)
Ċ	Install a cable clamp where the power supply enters the garbage disposal. BMC 16.04.060(c)
	Furnace Closet: See other requirements. No violations noted.
C	Hallway: Repair or replace existing smoke detector in a manner so that it functions as intended. IC 22-11-18-3.5
C	Hall Bath: Repair the sink faucet to eliminate the constant dripping. BMC 16.04.060(c)
C	Repair/replace the leaking "p" trap under the sink, came apart. BMC 16.04.060 (c)
C	Replace the rattling exhaust fan. BMC 16.04.060 (c)
C	Repair the tub faucet to eliminate the constant dripping. BMC 16.04.060(c)
C	The water supply system shall be installed and maintained to provide a supply of water to plumbing fixtures devices and appurtenances in sufficient volume and at pressures adequate to enable the fixtures to function properly, safely, and free from defects and leaks (repair tub faucet in a manner so that there is adequate water pressure and volume) . BMC 16.04.060(c)
	L Bedroom: No violations noted.
C	Repair the damaged door casing and repair the door to latch properly. BMC 16.04.060 (a)

Furnace Closet: See other requirements.

Unit 14 Living Room: Secure the loose receptacle on the east wall. BMC 16.04.060 (b) Kitchen: Secure the loose sink faucet handle. BMC 16.04.060 (c) Replace the defective GFCI receptacle on the south wall. BMC 16.04.060 (b) Furnace Closet: See other requirements. No violations noted. Hallway: No violations noted. Secure the loose toilet to its mountings. BMC 16.04.060 (c) Repair the tub faucet to eliminate the constant dripping. BMC 16.04.060(c) Interior walls shall be free of holes, cracks, peeling paint and/or deteriorated drywall/plaster, above the tub. BMC 16.04.060(a) Repair the surface of the ceiling to be free of holes, cracks, peeling paint and/or sagging materials, above the tub. BMC 16.04.060(a) L Bedroom: Secure the loose hinges on the door and repair the door to latch properly. BMC 16.04.060 (a) Replace the missing receptacle cover plates. BMC 16.04.060 (b)

Replace the missing door stop trim. BMC 16.04.060 (a)

<u>Unit 22</u>

Living Room:

Secure the loose receptacle on the north wall. BMC 16.04.060 (b)

Kitchen, Furnace Closet, Hallway:

No violations noted.

Hall Bath:

Secure the loose sink to the wall. BMC 16.04.060 (c)

L Bedroom, R Bedroom:

No violations noted.

Unit 24

Living Room, Kitchen. Furnace Closet:

No violations noted.

C	Hallway: Repair or replace existing smoke detector in IC 22-11-18-3.5	a manner so that it functions as intended.
C	Hall Bath: Secure the loose toilet to its mountings. BM	IC 16.04.060 (c)
C	Seal edge of floor covering adjacent to bath	tub. BMC 16.04.060(a)
C	Repair the surface of the ceiling to be free c tub. BMC 16.04.060(a)	f holes, cracks, peeling paint and/or sagging materials, above the
C	L Bedroom: Secure the loose hinges on the door and rep	air the door to latch properly. BMC 16.04.060 (a)
	R Bedroom: No violations noted.	
Mc.	Unit 34 Living Room: Secure the loose receptacle on the south wa	II. BMC 16.04.060 (b)
	<u>Kitchen:</u> Repair the left front burner to light as intend	ded. BMC 16.04.060 (c)
MC.	Repair the torn linoleum at the kitchen door	. BMC 16.04.060 (a)
10	<u>Furnace Closet:</u> See other requirements. Maintain minimum clearances from combust	ibles:
7	Fuel-fired appliances:Single-wall vent connectors:	36" clearance from combustible storage 1" clearance from Flow Guard Gold CPVC 6" clearance for other combustibles
	Double-wall vent connectors:Draft hood:BMC 16.04.060(c)	1" clearance for all combustibles 6" clearance for all combustibles
C	Hallway: Install/replace batteries in smoke detectors	so that they function as intended. IC 22-11-18-3.5
C	Replace the torn linoleum. BMC 16.04.060	(a)
C	Hall Bath: Secure the loose toilet to its mountings. BM	IC 16.04.060 (c)
C	Secure the loose toilet séat. BMC 16.04.060) (a)
	R Bedroom, L Bedroom: No violations noted.	
	Unit 32 Living Room: No violations noted.	•

C	<u>Kitchen</u> : Properly install or replace the aerator on the sink faucet so that it functions as intended. BMC 16.04.060(c)
C	Replace the failing sprayer leaks and works intermittently. BMC 16.04.060 (c)
C	Install a cable clamp where the power supply enters the garbage disposal. BMC 16.04.060(c)
	Furnace Closet, Hallway: No violations noted.
C	Hall Bath: Repair the sink faucet to eliminate the constant dripping. BMC 16.04.060(c)
	Secure the loose toilet to its mountings. BMC 16.04.060 (c)
Č	Remove the old caulk and install new caulk at the top of the tub and in the corner. BMC 16.04.060 (a)
C	Repair/replace the broken towel rack. BMC 16.04.060 (a)
C	<u>L Bedroom:</u> Secure the loose receptacle on the east wall. BMC 16.04.060 (b)
C	R Bedroom: Secure the loose receptacle on the east wall. BMC 16.04.060 (b)
C	Secure the loose 2 nd level handrail. BMC 16.04.060 (b)
N/C	EXTERIOR: Trim all tree branches away from the siding and roofline to maintain a 3' clearance, NW corner of structure. BMC 16.04.040(e)
1/1	Seal around all of the windows in this complex to be weather tight. BMC 16.04.050(a)
10	Re-install all of the improperly installed A/C vents on the 3 rd level. BMC 16.04.050(a) S. EMD AT 70 rd
	Repair the failing downspout on the SW corner of structure. BMC 16.04.050(a)
(All residential rental unit premises which contain trees shall maintain the trees in good health so that they

pose no danger to persons or property. Remove the dead tree on the SE corner of property. BMC 16.04.040(e)

OTHER REQUIREMENTS

Furnace Inspection Documentation x 12

Thoroughly clean and service the furnace, inspect and test shut off valves for proper operation. Documentation from a professional HVAC contractor for this service is acceptable and encouraged. Servicing shall include a test for carbon monoxide. Acceptable levels of carbon monoxide are as follows:

Desired level:

0 parts per million (ppm)

Acceptable level in a living space:

9 ppm

Maximum concentration for flue products:

50 ppm

BMC 16.01.060(f), BMC 16.04.060(c), BMC 16.04.060(b)

Tenants and Owners Rights and Responsibilities Summary

A completed copy of the Tenants and Owners Rights and Responsibilities Summary must be provided to this office within 60 days of the date of the inspection or a \$25.00 fine will be levied. BMC 16.03.060(c) and BMC 16.10.030(b)

Inventory Damage List

The owner or his agent shall contact the tenant and arrange a joint inspection of the premises to occur within ten days of the tenant's occupancy of the rental unit. The owner or his agent and the tenant shall at that time jointly complete an inventory and damage list, and this shall be signed by all parties to the tenancy agreement. Duplicate copies of the inventory and damage list shall be retained by all parties and shall be deemed a part of the tenancy agreement. A completed copy of the Inventory & Damage List must be provided to the office within 60 days of the date of the inspection or a \$25.00 fine will be levied. BMC 16.03.050(e) and BMC 16.10.030(b)

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.03.030(d): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner and the agent, the occupant load of the unit, the number of bedrooms, the expiration date of the permit, and any variances that have been granted for the property. BMC 16.03.030(c)

This is the end of this report.



Board of Housing Quality Appeals Staff Report: Petition for Extension of Time

Meeting Date:

September 18th, 2019

Petition Type:

An extension of time to complete repairs.

Petition Number:

19-TV-66

Address:

2663 E. 7th Street.

Petitioner:

Michelle Mosier

Inspector:

Kenny Liford/Matt Swinney/Dee Wills

Staff Report:

June 7th, 2018 Completed Cycle Inspection Report

August 5th, 2019 BHQA application received

Owner has requested an extension of time to complete repairs due to turnover and the loss of a maintenance person.

Staff recommendation: Grant the request.

Conditions: Have all repairs completed and a re-inspection scheduled by the deadline listed below.

Compliance Deadline: October 1st, 2019 To call and schedule re-inspection for all repairs.

Attachments: Cycle report, BHQA Appeal





hand@bloomington.in.goPY: Property Address: Park Doral Apartments Petitioner's Name: Michelle Mosier Address: 2663 E 7th Street City: Bloomington State: Indiana Zip Code: 47408 Phone Number: 8123368208 E-mail Address: parkdoral@crerentals.com Owner's Name: CRE Rentals - Maribeth Coller Address: 400 E 3rd St. Suite 1 City: Bloomington State: Indiana **Zip Code:** 47401 **Phone Number:** 8123321509 E-mail Address: dan@crerentals.com 104 unit apartments complex Occupants:

The following conditions must be found in each case in order for the Board to consider the request:

- 1. That the exception is consistent with the intent and purpose of the housing code and promotes public health, safety, and general welfare.
- That the value of the area about the property to which the exception is to apply will not be adversely affected.

Identify the variance type that you are requesting from the following drop down menu:

Variance Type: An extension of time to complete repairs. (Petition Type: TV)



Reminder:

A \$20.00 filing fee must be submitted with the Appeal Application or the application will not be considered to be complete! A completed application has to be submitted prior to the meeting application deadline in order to be placed on that months agenda!

(Will be assigned by BHQA)

Petition Number: 19-TV-66

In the space provided below please write a brief narrative regarding your request. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting. The following information must be included dependent upon the type of variance you are requesting:

- A. An extension of time to complete repairs, (Petition type: TV)
 - 1. Specify the items that need the extension of time to complete.
 - 2. Explain why the extension is needed.
 - 3. Specify the time requested.
- B. A modification or exception to the Housing Property Maintenance Code. (Petition type: V)
 - 1. Specify the code reference number you are appealing.
 - Detail why you are requesting the variance.
 - 3. Specify the modifications and or alterations you are suggesting.
- C. Relief from an administration decision. (Petition type: AA)
 - 1. Specify the decision being appealed and the relief you are seeking.
- D. Rescind a variance. (Petition type: RV)
 - 1. Detail the existing variance.
 - Specify the reason the variance is no longer needed.

ne (Print): Michelle Mosier portant information regarding this application format:	Date:	815119
nature (Required): Michelle Mosseur		
·-		
partment turnover. The also recently lost a maintenance tech. Ashab for 45 days	•	

- (e.g. postal mail),
- 2. This document may be saved on your computer for future use, however, any data that you have entered will not be saved.





City Of Bloomington Housing and Neighborhood Development RENTAL INSPECTION INFORMATION

JUN 1 3 2019

Maribeth Coller 400 E. 3rd Street Suite 1 Bloomington, IN 47401

RE: 2663 E 7th ST

Please find the enclosed Rental Inspection Report which contains pertinent information about the Cycle Inspection that was recently conducted at the above referenced property. The inspector has listed all noted violations and recommendations on the enclosed Rental Inspection Report. You have sixty (60) days from the date of this letter to correct the violations listed on the report.

Once violations have been corrected, it is your responsibility to call the Housing and Neighborhood Development office within this 60 day window but no later that AUG 1 2 2019 schedule a re-inspection. You have the right to appeal any violation of Bloomington Municipal Code Title 16 noted on the rental inspection report to the Board of Housing Quality Appeals.

This report is issued in accordance with BMC 16.10.020 and 16.10.040 of the Residential Rental Unit and Lodging Establishment Inspection Program. Residential Rental Occupancy Permits will not be issued until all interior and exterior violations have been corrected, and all fees have been paid. Bloomington Municipal Code requires that all violations of all Titles of the BMC must be in compliance before a permit will be issued. Please be advised that non-compliance by the deadlines listed in this letter may limit the permit period to a maximum of three (3) years.

If the owner's or agent's contact information has changed since your last inspection, please submit a new registration form to the HAND Department. The registration must be signed by the owner of the property, not the agent. All rental forms and documents can be found at www.bloomington.in.gov/hand. If you do not have access to the internet, you may contact HAND at 812-349-3420 and forms will be provided.

If you have any questions regarding the permit process, please call weekdays between 8:00 a.m. and 5:00 p.m., at (812) 349-3420.

Sincerely,

Housing & Neighborhood Development
Encl:Inspection Report,
Xc:Coller, Maribeth: 400 E. 3rd Street, Suite 1, Bloomington, IN 47401



City Of Bloomington Housing and Neighborhood Development

CYCLE INSPECTION REPORT

1659

Owner(s)
Maribeth Coller
400 E. 3rd Street Suite 1
Bloomington, IN 47401

Agent
Coller, Maribeth
400 E. 3rd Street, Suite 1
Bloomington, IN 47401

Prop. Location: 2663 E 7th ST Number of Units/Structures: 104/4

Units/Bedrooms/Max # of Occupants: Bld 1: Bld 1: 8/3/5 16/2/5 6/1/5 1/Eff/5, Bld 2: 6/3/5 11/2/5 3/1/5,

Bld 3: 6/3/5 12/2/5 2/1/5 1/Eff/5, Bld 4: 10/3/5 17/2/5 3/1/5 2/Eff/5

Date Inspected: 06/03/2019 Primary Heat Source: Gas Property Zoning: RH Number of Stories: 2 Inspector: Wills/ Swinney/ Liford Foundation Type: Basement

Attic Access: Yes

Accessory Structure: None

Monroe County Assessor's records indicate this structure was built in 1970. There are no minimum requirements for emergency egress at the time of construction.

Typical Egress:

Lower Level Sliding Windows:

Existing Egress Window Measurements:

Height: 44.50 inches Width: 33.50 inches Sill Height: 35 inches Openable Area: 10.35 sq. ft.

Upper Level Single Hung Windows:

Height: 21 inches
Width: 31.50 inches
Sill Height: 14 inches
Openable Area: 4.59 sq. ft.

Lower Level Efficiency Units Sliding Windows:

Height: 22 inches Width: 16 inches

Sill Height: 54.50 inches Openable Area: 2.44 sq. ft.

At the time this structure was built, there were no code requirements for emergency egress for a sleeping room. The Housing & Neighborhood Development Department strongly recommends that the sleeping room egress windows for the efficiency units be modified or replaced with a larger window to aid in emergency escape, BMC-16.04.020

INTERIOR

Building 2679

Unit K

Kitchen

Repair garbage disposal to function as intended. BMC 16.04.060(c)

Properly ground and secure the electrical receptacle. If the receptacle is on an ungrounded system, it is acceptable to install a 2-pole, ungrounded receptacle, or a GFCI receptacle. If a GFCI receptacle is installed, mark receptacle with the wording "no equipment ground". BMC16.04.020(a)(5); 2009 IEC Article 406.3(B)Grounding & 2009 IEC Article 406.3 (D)Replacements

Replace existing smoke detector with a new smoke detector. IC 22-11-18-3.5

Unit B

Kitchen

Eliminate all unused openings in the electric service panel by installing approved rigid knockout blanks. BMC 16.04.060(b)

Front Bedroom

Every window shall have a functioning locking device, window latch and shall be maintained in good condition. Window locks in rental units shall be capable of tightly securing the window and shall be openable without special knowledge or effort. BMC 16.04.060(b)

Unit C

Living Room

Properly repair/ replace the broken handle for the sliding glass door so that it functions as intended. BMC 16.04.060(a)

Unit D

No violations noted.

Unit E

Front Left Bedroom

Properly repair/replace the window so that it functions as intended. (off track) BMC 16.04.060(b)

Unit F

Living Room

The sliding glass door was not inspected at the time of this inspection, as it was not accessible. (blocked) The sliding glass door must be inspected and brought into compliance with-in the same 60 day deadline as the remainder of this property. BMC 16.03.040

Unit G

Front Left Bedroom

This window was not accessible at the time of this inspection. (blocked) This window must be brought into compliance with-in the same 60 day deadline as the remainder of this property. BMC 16.03.040

Unit H

Bedrooms

The windows were not accessible at the time of this inspection. (blocked) The windows must be brought into compliance with-in the same 60 day deadline as the remainder of this property. BMC 16.03.040

Unit I, Unit J

No violations noted.

Laundry/ Utility Room

No violations noted.

Building 2677

Unit A

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install new smoke detectors in an approved locations. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Unit B

Hallway

Replace the missing protective cover for the light fixture. BMC 16.04.060(c)

Front Right Bedroom

This window was not accessible at the time of this inspection. (blocked) This window must be brought into compliance with-in the same 60 day deadline as the remainder of this property. BMC 16.03.040

Back Bedroom

Every window shall have a functioning locking device, window latch and shall be maintained in good condition. Window locks in rental units shall be capable of tightly securing the window and shall be openable without special knowledge or effort. BMC 16.04.060(b)

Unit C

Living Room

Every door which connects a rental unit with any area exterior to the unit shall have a functioning locking device. Door locks in rental units shall be capable of tightly securing the door and shall be openable from the inside without the use of a key, special knowledge or effort. Repair/ replace the locking mechanism for the sliding glass door. BMC 16.04.060(a), BMC 16.04.060(b)

Kitchen

It is strongly recommended that a minimum 1A 10BC classification fire extinguisher be mounted in a visible, accessible location, in or adjacent to the kitchen, away from the range, and in the path of egress.

Eliminate all unused openings in the electric service panel by installing approved rigid knockout blanks. BMC 16.04.060(b)

Hallway

Repair or replace existing smoke detector in a manner so that it functions as intended. IC 22-11-18-3.5

Repair or replace door knob/lock assembly in a manner so that it functions as intended. BMC 16.04.060(a)

Unit D

Hallway

Replace the missing smoke detector. IC22-11-18-3.5

Back (Master) Bedroom

Every window shall be capable of being easily opened and held in position by its own hardware. BMC 16.04.060(b)

Unit E

Kitchen

Repair garbage disposal to function as intended. BMC 16.04.060(c)

Bathroom

Seal edge of floor covering adjacent to bathtub. BMC 16.04.060(a)

Front Left Bedroom

This window was not accessible at the time of this inspection. (blocked) This window must be brought into compliance with-in the same 60 day deadline as the remainder of this property. BMC 16.03.040

Master Bathroom

Properly seal the entire perimeter of the tub/shower including the floor. BMC 16.04.060(a)

Unit F

Eliminate all unused openings in the electric service panel by installing approved rigid knockout blanks. BMC 16.04.060(b)

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install new smoke detectors in an approved locations. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Front Right Bedroom

This window was not accessible at the time of this inspection. (blocked) This window must be brought into compliance with-in the same 60 day deadline as the remainder of this property. BMC 16.03.040

Unit G

Living Room

Properly secure the loose sliding door locking mechanism so that it functions as intended. BMC. 16.04.060(b)

Front Left Bedroom

Properly repair the right electrical outlet to be flush against the wall so that it functions as intended. BMC 16.04.060(b)

Scrape and paint interior surfaces where paint is peeling or bare surfaces are exposed around the window. BMC 16.04.060(f)

Unit H

Hallway

Replace the missing smoke detector. IC22-11-18-3.5

All other smoke detector in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install new smoke detectors in an approved locations. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Front Right Bedroom

This window was not accessible at the time of this inspection. (blocked) This window must be brought into compliance with-in the same 60 day deadline as the remainder of this property. BMC 16.03.040

Unit I

Center Left Bedroom

Properly repair the window so that it functions as intended. (spring broken) BMC 16.04.060(b)

Unit J

No violations noted.

Laundry/ Utility Room

No violations noted.

Building 2675

Unit K

No violations noted.

Unit A

Kitchen

Provide electrical power to the receptacle (left of sink) so that it functions as intended. BMC 16.04.060(c)

Unit B

Living Room

Remove the gas tank and grill from the interior living space. Fueled equipment, including but not limited to motorcycles, mopeds, lawn-care equipment and portable cooking equipment, shall not be stored, operated or repaired within a building. BMC 16.04.020(a)(3) (2014 IFC 313.1, 313.2)

Kitchen

Properly secure the sink faucet assembly so that it functions as intended. BMC 16.04.060(c)

Front Right Bedroom

This window was not accessible at the time of this inspection. (blocked) This window must be brought into compliance with-in the same 60 day deadline as the remainder of this property. BMC 16.03.04

Unit C

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install new smoke detectors in an approved locations. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Unit D

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install new smoke detectors in an approved locations. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Front Right Bedroom

This window was not accessible at the time of this inspection. (blocked) This window must be brought into compliance with-in the same 60 day deadline as the remainder of this property. BMC 16.03.040

Unit E

No violations noted.

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install new smoke detectors in an approved locations. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Bathroom

Properly complete the ceiling repair above the shower surround. BMC 16.04.060(a)

Unit G

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install new smoke detectors in an approved locations. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Bathroom

Properly secure the loose electrical outlet so that it functions as intended. BMC 16.04.060(b)

Unit H

Front Bedroom, Rear Bedroom\

The windows were not accessible at the time of this inspection. (blocked) The windows must be brought into compliance with-in the same 60 day deadline as the remainder of this property. BMC 16.03.040

Unit I

No violations noted.

Unit J

Kitchen

Repair the faucet sprayer on the sink to function as intended by the manufacturer, or remove and properly terminate the line for the sprayer. BMC 16.04.060(c)

Laundry / Utility Room

No violations noted.

Building 2671

Unit A

Kitchen

Properly re-caulk around the countertop to eliminate water infiltration. BMC 16.04.060(a)

Scrape and paint interior surfaces above the sink countertop where paint is peeling or bare surfaces are exposed. BMC 16.04.060(f)

Unit B

Hallway

Repair or replace existing smoke detector in a manner so that it functions as intended. IC 22-11-18-3.5

Furnace Closet

Maintain minimum clearances from combustibles:

Fuel-fired appliances:

36" clearance from combustible storage

Single-wall vent connectors:

1" clearance from Flow Guard Gold CPVC

6" clearance for other combustibles

Double-wall vent connectors:

1" clearance for all combustibles

Draft hood:

6" clearance for all combustibles

BMC 16.04.060(c)

Unit C

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install new smoke detectors in an approved locations. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Living Room

Secure the register vent cover. BMC 16.04.060(a)

Bathroom

Properly secure the loose electrical outlet so that it functions as intended. BMC 16.04.060(b)

Unit D

Kitchen

Repair garbage disposal to function as intended. BMC 16.04.060(c)

Repair or replace existing smoke detector in a manner so that it functions as intended, IC 22-11-18-3.5

Bathroom

Replace non-functioning or incorrectly wired GFCI receptacle(s), per Indiana Electric Code requirements. BMC 16.04.020 (IEC 210.8) and BMC 16.04.060(b)

Master Bathroom

Properly repair, then clean and surface coat damaged or stained ceiling area. BMC 16.04.060(a)

Unit E

Kitchen

Properly re-caulk around the countertop to eliminate water infiltration. BMC 16.04.060(a)

Hallway

Repair or replace existing smoke detector in a manner so that it functions as intended. IC 22-11-18-3.5

Unit F

No violations noted.

Unit G

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will notguarantee it to provide adequate protection. Install new smoke detectors in an approved locations. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Kitchen

The electrical panel box was not accessible at the time of this inspection. (blocked) The electrical panel box must be brought into compliance with-in the same 60 day deadline as the remainder of this property. BMC 16.03.040

Bathroom.

Clean and service the exhaust fan so that it functions as intended. BMC 16.04.060(c)

Front Left Bedroom

Every window shall be capable of being easily opened and held in position by its own hardware. BMC 16.04.060(b)

Rear Bedroom

Properly repair/ replace the window so that it functions as intended. BMC 16.04.060(b)

Deck

Charcoal burners and other open-flame cooking devices shall not be operated on combustible balconies or within 10 feet of combustible construction.

Exceptions:

1. One & Two family dwellings

2. Where the buildings & decks are protected by an automatic sprinkler system

LP gas burners shall not be located on combustible balconies or within 10 feet of combustible construction.

Exception:

1. One and two family dwellings,

2. Where buildings, balconies, and decks are protected by an automatic sprinkler system. Charcoal grills may be stored in these locations. Gas grills may be stored in these locations without the propane tank attached. (Propane tanks shall not be stored in the living space, garage or storage shed).

BMC 16.04.020(a)(3), Indiana Fire Code Sec. 308.3.1 & Sec. 308.3.1.1

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install new smoke detectors in an approved locations. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Furnace Closet

Maintain minimum clearances from combustibles:

Fuel-fired appliances:

36" clearance from combustible storage

Single-wall vent connectors:

1" clearance from Flow Guard Gold CPVC

6" clearance for other combustibles

Double-wall vent connectors:

1" clearance for all combustibles

Draft hood:

6" clearance for all combustibles

BMC 16.04.060(c)

Living Room

Every door which connects a rental unit with any area exterior to the unit shall have a functioning locking device. Door locks in rental units shall be capable of tightly securing the door and shall be openable from the inside without the use of a key, special knowledge or effort. Repair/ replace the locking mechanism for the sliding glass door. BMC 16.04.060(a), BMC 16.04.060(b)

Unit I

Living Room

Every door which connects a rental unit with any area exterior to the unit shall have a functioning locking device. Door locks in rental units shall be capable of tightly securing the door and shall be openable from the inside without the use of a key, special knowledge or effort. Repair/replace the locking mechanism for the sliding glass door. BMC 16.04.060(a), BMC 16.04.060(b)

Repair or replace existing smoke detector in a manner so that it functions as intended. IC 22-11-18-3.5

Back Bedroom

Replace damaged or torn window screen(s). BMC 16.04.060(a)

Deck

Properly secure the cover for the ac Unit. BMC 16.04.060(c)

No violations noted.

Building 2673

Laundry/ Utility Room

No violations noted.

Every occupant of a structure or part thereof shall keep that structure or part thereof which the tenant occupies, controls or uses in a clean and sanitary condition. Properly clean the dirty/soiled floor covering. BMC 16.04.060(d)

Unit A

No violations noted.

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install new smoke detectors in an approved locations. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install new smoke detectors in an approved locations. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Kitchen

Repair garbage disposal to function as intended. BMC 16.04.060(c)

Bathroom

Repair the surface of the ceiling to be free of cracks, peeling paint and/or sagging materials. BMC 16.04.060(a)

Rear Bedroom

This window was not accessible at the time of this inspection. (plastic) This window must be brought into compliance with-in the same 60 day deadline as the remainder of this property. BMC 16.03.040

Unit D

Living Room

Every door which connects a rental unit with any area exterior to the unit shall have a functioning locking device. Door locks in rental units shall be capable of tightly securing the door and shall be openable from the inside without the use of a key, special knowledge or effort. Repair/replace the locking mechanism for the sliding glass door. BMC 16.04.060(a), BMC 16.04.060(b)

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install new smoke detectors in an approved locations. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Unit F

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install new smoke detectors in an approved locations. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Unit G

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install new smoke detectors in an approved locations. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Seal entire edge of floor covering and secure the loose tiles. BMC 16.04.060(a)

Unit H

Living Room

Repair/ replace the broken handle for the sliding glass door so that it functions as intended. BMC 16.04.060(a)

Center Bedroom

Repair/ replace the broken spring for the window so that it functions as intended. BMC 16.04.060(b)

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install new smoke detectors in an approved locations. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Furnace Closet

Properly secure the cover panels for the furnace and the AC unit. BMC 16.04.060(c)

Front Bedroom, Rear Bedroom

The windows were not accessible at the time of this inspection. (blocked) The windows must be brought into compliance with-in the same 60 day deadline as the remainder of this property. BMC 16.03.040

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install new smoke detectors in an approved locations. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

This window was not accessible at the time of this inspection. (blocked) This window must be brought into compliance with-in the same 60 day deadline as the remainder of this property. BMC 16.03.040

Building 2663

Unit A

Every window shall be capable of being easily opened and held in position by its own hardware. BMC 16.04.060(b)

Unit B

Every window shall be capable of being easily opened and held in position by its own hardware. BMC 16.04.060(b)

The seals on the window glass in this room have failed causing the transparent quality of the window to be significantly reduced. Repair or replace the window(s) in a manner that restores the transparent quality of the window(s) and allows the window(s) to function as intended. BMC16.04.060(a)

Unit C

Left side window shall be capable of being easily opened and held in position by its own hardware. BMC 16.04.060(b)

The seals on the window glass in this room have failed causing the transparent quality of the window to be significantly reduced. Repair or replace the window(s) in a manner that restores the transparent quality of the window(s) and allows the window(s) to function as intended. BMC16.04.060(a)

Unit D

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Unit E

No violations noted.

Unit F

Kitchen

Replace the missing protective cover for the sink light fixture. BMC 16.04.060(c)

Right side window shall be capable of being easily opened and held in position by its own hardware. BMC 16.04.060(b)

The smoke detector in this room appears to be more than ten years old and the manufacturer will not. guarantee it to provide adequate protection. Install a new smoke detector in an approved location. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Bathroom

Properly seal the entire perimeter of the tub/shower including the floor. BMC 16.04.060(a)

Unit G

No violations noted.

Unit H

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Repair the exhaust fan to eliminate excessive noise. BMC 16.04.060(c)

Kitchen

Secure loose electrical receptacle to the right of the sink. BMC 16.04.060(b)

Weatherproof outlet cover for exterior outlet missing. BMC 16.04.050(b)

Unit I The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Deck Utility Room

Fuel fired furnace and water heater vent connectors/flue piping shall be installed without dips or sags and shall slope upward toward the vent or chimney at least 1/4 inch per foot (2000 IFG 503.10.8). Replace or reconfigure the existing vent connectors/flue piping in a manner that meets the abovementioned criteria. BMC 16.04.060(c)

Bedroom 1

Replace the broken window on the upper left side. BMC 16.04.060(a)

Install/replace batteries in smoke detectors so that they function as intended. IC 22-11-18-3.5

Unit J

Bedroom

Properly repair or replace loose, damaged, or missing floor covering. BMC 16.04.060(a)

Left side window shall be capable of being easily opened and held in position by its own hardware. BMC 16.04.060(b)

The smoke detector in this room appears to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detector in an approved location. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Repair the water pressure to the sink faucet (very low). The water supply system shall be installed and maintained to provide a supply of water to plumbing fixtures, devices and appurtenances in sufficient volume and at pressures adequate to enable the fixtures to function properly, safely, and free from defects and leaks. BMC 16.04.060(c)

Properly repair or replace loose, damaged, or missing floor covering. BMC 16.04.060(a)

Building 2665

Laundry Room

Temperature/pressure relief (TPR) valve discharge tubes:

- shall not be reduced in size from the valve outlet
- shall be rigid galvanized, rigid copper, or any CPVC pipe
- shall not have a threaded discharge end
- drain by gravity
- shall have a minimum 1" air gap where discharging into a sanitary drain, or an approved air break
- shall extend to within 6" of floor. BMC 16.04.060(c)

Unit A

Living Room

Secure loose electrical receptacle. BMC 16.04.060(b)

Properly re-caulk around the countertop to eliminate water infiltration. BMC 16.04.060(a)

Bathroom

Repair the surface of the ceiling to be free of holes, cracks, peeling paint and/or sagging materials. BMC 16.04.060(a)

Unit B

Living Room

Secure loose electrical receptacle. BMC 16.04.060(b)

Bedroom 1

Every window shall be capable of being easily opened and held in position by its own hardware. BMC 16.04.060(b)

The seals on the window glass in this room have failed causing the transparent quality of the window to be significantly reduced. Repair or replace the window(s) in a manner that restores the transparent quality of the window(s) and allows the window(s) to function as intended. BMC16.04.060(a)

Unit C

Bedroom 2

The smoke detector in this room appears to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detector in an approved location. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Unit D

Kitchen

Repair garbage disposal to function as intended. BMC 16.04.060(c)

Bathroom

Repair the exhaust fan to eliminate excessive noise. BMC 16.04.060(c)

Every window shall be capable of being easily opened and held in position by its own hardware. BMC 16.04.060(b)

Bedroom 2

Install/replace batteries in smoke detectors so that they function as intended. IC 22-11- 18-3.5

Unit E

Bathroom

Interior walls by Toilet and tub shall be free of holes, cracks, peeling paint and/or deteriorated drywall/plaster. BMC 16.04.060(à)

Master Bathroom

Properly re-caulk around the countertop to eliminate water infiltration. BMC 16.04.060(a)

Repair the exhaust fan to eliminate excessive noise. BMC 16.04.060(c)

Hallway

The smoke detector in this room appears to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detector in an approved location. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Unit F

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Provide operating power to the smoke detector. IC 22-11-18-3.5

Properly re-caulk around the countertop to eliminate water infiltration. BMC 16.04.060(a)

Bedroom 1

Every window shall be capable of being easily opened and held in position by its own hardware. BMC 16.04.060(b)

Living Room

Secure HVAC return grille. BMC 16.04.060(c)

Unit G

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Living Room

Repair the sliding door to latch and function as intended. BMC 16.04.060(a)

Deck Utility Closet

A junction box shall be supplied at each conductor splice. BMC 16.04.060(b)

Unit H

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Living Room

Repair the sliding door to latch and function as intended. BMC 16.04.060(a)

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Living Room

Repair the sliding door to latch and function as intended. BMC 16.04.060(a)

Hallway

Secure loose electrical receptacle. BMC 16.04.060(b)

Install/replace batteries in smoke detectors so that they function as intended. IC 22-11-18-3.5

Bedroom 2

Replace existing smoke detector with a new smoke detector. IC 22-11-18-3.5

Bedroom 3

Repair or replace existing smoke detector in a manner so that it functions as intended. IC 22-11-18-3.5

Bedroom 3 Bathroom

Clean and service the exhaust fan so that it functions as intended, BMC 16.04.060(c)

Repair the water pressure to the sink faucet (very low). The water supply system shall be installed and maintained to provide a supply of water to plumbing fixtures, devices and appurtenances in sufficient volume and at pressures adequate to enable the fixtures to function properly, safely, and free from defects and leaks. BMC 16.04.060(c)

Unit J

Living Room

Repair the sliding door to latch and function as intended. BMC 16.04.060(a)

Building 2661

Unit A

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Repair the exhaust fan to eliminate excessive noise. BMC 16.04.060(c)

Unit B

Deck Utility Closet

Secure front cover on furnace. BMC 16.04.060(c)

Living Room

Repair the sliding door to latch and function as intended. BMC 16.04.060(a)

Every window shall be capable of being easily opened and held in position by its own hardware. BMC 16.04.060(b)

Unit C

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Repair the sliding door to latch and function as intended. BMC 16.04.060(a)

Repair or replace existing smoke detector in a manner so that it functions as intended. IC 22-11-18-3.5

Properly seal the entire perimeter of the tub/shower including the floor. BMC 16.04.060(a)

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Living Room

Repair the sliding door to latch and function as intended. BMC 16.04.060(a)

Bathroom

Interior walls by the tub shall be free of holes, cracks, peeling paint and/or deteriorated drywall/plaster. BMC 16.04.060(a)

Bedroom 2

Install/replace batteries in smoke detectors so that they function as intended. IC 22-11-18-3.5

Living Room

Replace missing outlet cover plate. BMC 16.04.060(b)

Unit E

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Unit F

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Hallway

Replace the missing smoke detector. The missing smoke detector was hard wired and must be replaced with a hard wired model. IC 22-11-18-3.5

Bathroom

Repair the tub faucet to eliminate the constant dripping. BMC 16.04.060(c)

Unit G

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Bathroom

Properly seal the entire perimeter of the tub/shower including the floor. BMC 16.04.060(a)

Unit H

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Master Bathroom

Properly seal the entire perimeter of the tub/shower including the floor. BMC 16.04.060(a)

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Deck Utility Closet

Secure front cover on the furnace. BMC 16.04.060(c)

Living Room

Repair sliding door to latch and function as intended. BMC 16.04.060(a)

Bathroom

Repair the exhaust fan to eliminate excessive noise. BMC 16.04.060(c)

Unit J

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Living Room

Repair the sliding door to latch and function as intended. BMC 16.04.060(a)

Properly seal the entire perimeter of the tub/shower including the floor. BMC 16.04.060(a)

Unit K

Bathroom_

Clean and service the exhaust fan so that it functions as intended. BMC 16.04.060(c)

Kitchen

Install a cable clamp where the power supply enters the garbage disposal. BMC 16.04.060(c)

Building 2667

Unit A

Kitchen

Provide a complete directory of all service panels and circuits. BMC 16.04.020(a) IEC 408.4

Bedroom 1

Every window shall be capable of being easily opened and held in position by its own hardware. BMC 16.04.060(b)

Hallway

Repair or replace existing smoke detector in a manner so that it functions as intended. IC 22-11-18-3.5

Unit B

Living Room

Repair the sliding door to latch and function as intended. BMC 16.04.060(a)

Hallway

The smoke detector in this room appears to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detector in an approved location. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Unit C

Kitchen

Provide a complete directory of all service panels and circuits. BMC 16.04.020(a) IEC 408.4

Install a cable clamp where the power supply enters the garbage disposal. BMC 16.04.060(c)

Bedroom 2

The seals on the window glass in this room have failed causing the transparent quality of the window to be significantly reduced. Repair or replace the window(s) in a manner that restores the transparent quality of the window(s) and allows the window(s) to function as intended. BMC16.04.060(a)

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Living Room

Repair the sliding door to latch and function as intended. BMC 16.04.060(a)

Kitchen

Eliminate all unused openings in the electric service panel by installing approved rigid knockout blanks. BMC 16.04.060(b)

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Bedroom 1

The seals on the window glass in this room have failed causing the transparent quality of the window to be significantly reduced. Repair or replace the window(s) in a manner that restores the transparent quality of the window(s) and allows the window(s) to function as intended. BMC16.04.060(a)

Bathroom_

Properly seal the entire perimeter of the tub/shower including the floor. BMC 16.04.060(a)

Properly re-caulk around the countertop to eliminate water infiltration. BMC 16.04.060(a)

Bedroom 2

The seals on the window glass in this room have failed causing the transparent quality of the window to be significantly reduced. Repair or replace the window(s) in a manner that restores the transparent quality of the window(s) and allows the window(s) to function as intended. BMC16.04.060(a)

Bedroom 3

The seals on the window glass in this room have failed causing the transparent quality of the window to be significantly reduced. Repair or replace the window(s) in a manner that restores the transparent quality of the window(s) and allows the window(s) to function as intended. BMC16.04.060(a)

Master Bathroom

Properly seal the entire perimeter of the tub/shower including the floor. BMC 16.04.060(a)

Properly re-caulk around the countertop to eliminate water infiltration. BMC 16.04.060(a)

Unit F

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Kitchen

Install a cable clamp where the power supply enters the garbage disposal. BMC 16.04.060(c)

Bathroom

Properly seal the entire perimeter of the tub/shower including the floor. BMC 16.04.060(a)

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Bathroom

Properly seal the entire perimeter of the tub/shower including the floor. BMC 16.04.060(a)

Bedroom 2

Every window shall be capable of being easily opened and held in position by its own hardware. BMC 16.04.060(b)

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Kitchen

Clean and service the range hood exhaust fan so that it functions as intended. BMC 16.04.060(c)

Repair the range hood light fixture to function as intended. BMC 16.04.060(b)

Bathroom

Properly seal the entire perimeter of the tub/shower including the floor. BMC 16.04.060(a)

Unit I

Living Room

Repair the sliding door to latch and function as intended. BMC 16.04.060(a)

Kitchen

Install a cable clamp where the power supply enters the garbage disposal. BMC 16.04.060(c)

Master Bedroom

Right side window shall be capable of being easily opened and held in position by its own hardware. BMC 16.04.060(b)

Master Bathroom

Properly seal the entire perimeter of the shower including the floor. BMC 16.04.060(a)

Bathroom

Properly seal the entire perimeter of the tub/shower including the floor. BMC 16.04.060(a)

Unit J

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Kitchen

Provide a complete directory of all service panels and circuits. BMC 16.04.020(a) IEC 408.4

Bathroom

Interior walls by the tub shall be free of holes, cracks, peeling paint and/or deteriorated drywall/plaster. BMC 16.04.060(a)

Building 2669

Unit A

Deck Utility Closet

Repair the surface of the ceiling around through penetration to be free of holes, cracks, peeling paint and/or sagging materials. BMC 16.04.060(a)

Deck Storage Closet

Repair/replace the damaged door. BMC 16.04.060(a)

Bathroom

Properly seal the entire perimeter of the tub/shower including the floor. BMC 16.04.060(a)

Unit B

Deck Utility Closet

Replace the rotted flue pipe for the furnace. BMC 16.04.060(c)

Kitchen

Repair the faucet sprayer on the sink to be secure and function as intended by the manufacturer, or remove and properly terminate the line for the sprayer. BMC 16.04.060(c)

Bedroom_

The seals on the window glass in this room have failed causing the transparent quality of the window to be significantly reduced. Repair or replace the window(s) in a manner that restores the transparent quality of the window(s) and allows the window(s) to function as intended. BMC16.04.060(a)

Hallway

Repair or replace existing smoke detector in a manner so that it functions as intended. IC 22-11-18-3.5

Unit C

Living Room

Repair the sliding door to latch and function as intended. BMC 16.04.060(a)

Install a cable clamp where the power supply enters the garbage disposal. BMC 16.04.060(c)

Bedroom 1

The smoke detector in this room appears to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detector in an approved location. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Bedroom 2

The smoke detector in this room appears to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detector in an approved location. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Properly repair or replace loose, damaged, or missing floor covering. BMC 16:04.060(a)

Unit D

Bathroom

Reattach cove base behind toilet. BMC 16.04.060(a)

Bedroom 3 Master

The smoke detector in this room appears to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detector in an approved location. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Master Bathroom

Properly seal the entire perimeter of the tub/shower including the floor. BMC 16.04.060(a)

Unit E

Deck Utility Closet

Interior walls shall be free of holes, cracks, peeling paint and/or deteriorated drywall/plaster. BMC 16.04.060(a)

Kitchen

Replace the missing range hood filter. BMC 16.04.060(a)

Bathroom

Properly re-caulk around the countertop to eliminate water infiltration. BMC 16.04.060(a)

Interior walls by tub shall be free of holes, cracks, peeling paint and/or deteriorated drywall/plaster. BMC 16.04.060(a)

Unit F

Kitchen

Provide a complete directory of all service panels and circuits. BMC 16.04.020(a) IEC 408.4

Install a cable clamp where the power supply enters the garbage disposal. BMC 16.04.060(c)

Unit G

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Deck Utility Closet

Repair the surface of the at the flue stack to be free of holes, cracks, peeling paint and/or sagging materials. BMC 16.04.060(a)

Kitchen

Install a cable clamp where the power supply enters the garbage disposal. BMC 16.04.060(c)

Unit H

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Kitchen

Provide a complete directory of all service panels and circuits. BMC 16.04.020(a) IEC 408.4

Install a cable clamp where the power supply enters the garbage disposal. BMC 16.04.060(c)

Bathroom

Properly seal the entire perimeter of the tub/shower including the floor. BMC 16.04.060(a)

Master Bedroom

Properly seal the entire perimeter of the tub/shower including the floor. BMC 16.04.060(a)

Unit I

Deck Utility Closet

Repair the surface of the at the flue stack to be free of holes, cracks, peeling paint and/or sagging materials. BMC 16.04.060(a)

Unit J

The smoke detectors in this unit appear to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detectors in an approved locations. If wall mounted, they shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, they shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Deck Utility Closet

Repair the surface of the at the flue stack to be free of holes, cracks, peeling paint and/or sagging materials. BMC 16.04.060(a)

Kitchen_

Provide a complete directory of all service panels and circuits. BMC 16.04.020(a) IEC 408.4

Bedroom

The seals on the window glass in this room have failed causing the transparent quality of the window to be significantly reduced. Repair or replace the window(s) in a manner that restores the transparent quality of the window(s) and allows the window(s) to function as intended. BMC16.04.060(a)

EXTERIOR

Building 2661-2663-2665

Properly label gas service meters/disconnects with corresponding unit numbers. BMC 16.04.020

Building 2667-2669

Properly label gas service meters/disconnects with corresponding unit numbers. BMC 16.04.020

Properly seal the open pipe w/condensation line. (East side) BMC 16.04.050(a)

Trim all tree branches away from the siding and roofline to maintain a 3' clearance. BMC 16.04.040(e)

Building 2671-2673

Properly seal the openings where gas lines enter the building. (East Side). BMC 16.04.050(a)

Secure the loose fascia boards on the decks to the left and right of the entrance to 2673. BMC 16.04.050(a)

Scrape and paint exterior surfaces where paint is peeling or wood is exposed (Decks on west side of building). BMC 16.04.050(e)

Properly install approved exterior vent cover on the bathroom/laundry exhaust (West side). BMC 16.04.050(a)

Properly label gas service meters/disconnects with corresponding unit numbers. BMC 16.04.020

Building 2675-2677-2679

Repair/replace the rotten trim and brick mold around the entrance door to 2675. BMC 16.04.050(a)

Scrape and paint exterior surfaces where paint is peeling or wood is exposed (Decks to building 2675). BMC 16.04.050(e)

Properly seal the open pipe w/condensation line. (North side) BMC 16.04.050(a)

Replace the deteriorated glazing compound on the windows. BMC 16.04.050(a)

Trim all tree branches away from the siding and roofline to maintain a 3' clearance. BMC 16.04.040(e) Properly label gas service meters/disconnects with corresponding unit numbers. BMC 16.04.020

OTHER REQUIREMENTS

Furnace Inspection Documentation X 104

Thoroughly clean and service all furnaces, inspect and test shut off valves for proper operation. Documentation from a professional HVAC contractor for this service is acceptable and encouraged. Servicing shall include a test for carbon monoxide. Acceptable levels of carbon monoxide are as follows:

Desired level:

0 parts per million (ppm)

Acceptable level in a living space:

9 ppm

Maximum concentration for flue products:

50 ppm

BMC 16.01.060(f), BMC 16.04.060(c), BMC 16.04.060(b)

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.03.030(d): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner and the agent, the occupant load of the unit, the number of bedrooms, the expiration date of the permit, and any variances that have been granted for the property. BMC 16.03.030(c)

This is the end of this report.



Board of Housing Quality Appeals Staff Report: Petition for Extension of Time

Meeting Date:

September 18, 2019

Petition Type:

An extension of time to complete repairs.

Petition Number:

19-TV-68

Address:

857 Sherwood Hills Drive

Petitioner:

Christina Divine

Inspector:

Dee Wills

Staff Report:

April 11, 2019 Completed Cycle Inspection

August 07, 2019 Completed Reinspection

August 12, 2019 Received Application for Appeal

The petitioner is requesting an extension of time for the installation of a replacement window. The window has been ordered and arrived with Tommy D's Window company, however they are backed up on the installation of windows at this time. All other

items are in compliance.

Staff recommendation:

Grant the request.

Conditions:

Complete all repairs and schedule for re-inspection no later than the deadline stated below, or this case will be turned over to the City of Bloomington Legal Department for further action,

including, but not limited to, the possibility of fines.

Compliance Deadline:

November 18, 2019

Attachments:

Application for Appeal, Receipt/ Installation Order form, Cycle

Inspection Report

K



Application For Appear To The Board of Housing Quality Appeals P.O. Box 100 Bloomington, IN 47402 812-349-3420 hand@bloomington.in.gov

Petitioner's Name: Christina Divin	e			
Address: 3615 S Bluebird Ct				
City: Bloomington	State: Indiana	State: Indiana Zip Code: 47401		
Phone Number: (812) 369-8757	E-mail Address: christina.divine@comcast.net			
Owner's Name: Christina Divine	,			
Address: 3615 S Bluebird Ct				
City: Bloomington	State: Indiana	Zip Code: 47401		
Phone Number: 812-369-8757	E-mail Address: christin	a.divine@comcast.net		
Occupants: Nicholas Divine		·		

The following conditions must be found in each case in order for the Board to consider the request:

- 1. That the exception is consistent with the intent and purpose of the housing code and promotes public health, safety, and general welfare.
- 2. That the value of the area about the property to which the exception is to apply will not be adversely affected.

Identify the variance type that you are requesting from the following drop down menu:

Variance Type: An extension of time to complete repairs. (Petition Type: TV)

Reminder:

A \$20.00 filing fee must be submitted with the Appeal Application or the application will not be considered to be complete! A completed application has to be submitted prior to the meeting application deadline in order to be placed on that months agenda!

(Will be assigned by BHQA)

Petition Number: 19-7V - 68

In the space provided below please write a brief narrative regarding your request. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting. The following information must be included dependent upon the type of variance you are requesting:

- A. An extension of time to complete repairs. (Petition type: TV)
 - 1. Specify the items that need the extension of time to complete.
 - 2. Explain why the extension is needed.
 - 3. Specify the time requested.
- B. A modification or exception to the Housing Property Maintenance Code. (Petition type: V)
 - 1. Specify the code reference number you are appealing.
 - 2. Detail why you are requesting the variance.
 - 3. Specify the modifications and or alterations you are suggesting.
- C. Relief from an administration decision. (Petition type: AA)
 - 1. Specify the decision being appealed and the relief you are seeking.
- D. Rescind a variance. (Petition type: RV)
 - 1. Detail the existing variance.
 - 2. Specify the reason the variance is no longer needed.

ve included a copy of the window order showing the down pay	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
nature (Required): Chrestinae Deve	·	

2. This document may be saved on your computer for future use, however, any data that you have entered will not be saved.

Print Form

INSTALL ORDER

Tommy D's Windows Doors & More 3148 State Road 446

Bloomington, IN 47401 Phone: (812) 330-8898 (812) 330-8863 Fax:

To: Z06126 CHRISTINA DIVINE 3615 S BLUEBIRD CT

BLOOMINGTON

IN 47401.

Tommy 3148 S. State Road 446 D's Bloomington, In 47401

Windows, Doors & More, Inc.

Ship To: CHRISTINA DIVINE

857 SHERWOOD HILLS DR BLOOMINGTON

IN 47401

Ord #: 124976-0

Route: NONE

Page: 1 of 1

Order: 06/27/19 Sched: 07/08/19

Printed Date: 07/10/19 Time: 03:34 PM

0.00

619.30

207.00

412.30

Misc Charges..:

Order Total...:

Less Deposit..:

Balance Due...:

FOB: DL	VD	Via: Our Tru	ick ,	Phone:(812) 369-8757	 Contact	•		: U3:34 PM
ype: WH	SE	In: AS / Out:	AS	Terms: DUE ON RECEIPT	Your Or	der: DIVINE	CHRISTINA	
			<u></u>			. <u>Custome</u> PAYMENT DUE	er Instruct UPON DELIV	ions ERY
ne #	It	em Number		Description	luantity	II/M		
001.00	*124	976001.00	Fla 65- DP4 Sta Dou	Full Window, Nailing nge, 3001, R.O. 36" X 1/4", White, Low-E, Argon, 5, 45, Standard Glass, ndard Glass, Full Screen, ole Lock, Prime 4 9/16, No nannel Filler, 0.29, 0.28	Quantity 1.00	EA		
		,						
 -	-					Merchandis	:	619.30



RENTAL INSPECTION INFORMATION

APR 2 9 2019

Divine, Christina 3615 S. Bluebird Court Bloomington, IN 47401

RE: 857 E Sherwood Hills DR

Please find the enclosed Rental Inspection Report which contains pertinent information about the Cycle Inspection that was recently conducted at the above referenced property. The inspector has listed all noted violations and recommendations on the enclosed Rental Inspection Report. You have sixty (60) days from the date of this letter to correct the violations listed on the report.

Once violations have been corrected, it is your responsibility to call the Housing and Neighborhood Development office within this 60 day window but no later than **JUN 28 2019** to schedule a re-inspection. You have the right to appeal any violation of Bloomington Municipal Code Title 16 noted on the rental inspection report to the Board of Housing Quality Appeals.

This report is issued in accordance with BMC 16.10.020 and 16.10.040 of the Residential Rental Unit and Lodging Establishment Inspection Program. Residential Rental Occupancy Permits will not be issued until all interior and exterior violations have been corrected, and all fees have been paid. Bloomington Municipal Code requires that all violations of all Titles of the BMC must be in compliance before a permit will be issued. Please be advised that non-compliance by the deadlines listed in this letter may limit the permit period to a maximum of three (3) years.

If the owner's or agent's contact information has changed since your last inspection, please submit a new registration form to the HAND Department. The registration must be signed by the owner of the property, not the agent. All rental forms and documents can be found at www.bloomington.in.gov/hand. If you do not have access to the internet, you may contact HAND at 812-349-3420 and forms will be provided.

If you have any questions regarding the permit process, please call weekdays between 8:00 a.m. and 5:00 p.m., at (812) 349-3420.

Sincerely,

Housing & Neighborhood Development Encl:Inspection Report,







CYCLE INSPECTION REPORT

9336

Owner(s)

Divine, Christina 3615 S. Bluebird Court Bloomington, IN 47401

Prop. Location: 857 E Sherwood Hills DR

Number of Units/Structures: 1/1

Units/Bedrooms/Max # of Occupants: Bld 1: 1/2/5

Date Inspected: 04/11/2019 Primary Heat Source: Electric

Property Zoning: RM

Number of Stories: 2

Inspector: Dee Wills Foundation Type: Slab

Attic Access: Yes

Accessory Structure: None

The Monroe County Assessor's records indicate that this structure was built in 1998. Minimum egress requirements for a single family dwelling built at the time of construction.

Openable area: 4.75 Sq. Ft. Clear height: 22 inches Clear width: 20 inches

Sill height: not more than 44 inches above finished floor.

INTERIOR

Main Level

Living Room 12-10 x 10-6), 1/2 Bathroom, Furnace Closet, Laundry Closet, Kitchen (11-3 x 10-6) No violations noted.

Upper Level

Back Bedroom (13-10 x 9-4)

The smoke detector in this room appears to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detector in an approved location. If wall prounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall. IC 22-11-18-3.5

Replace the broken window pane. BMC 16.04.060(a)

Replace the missing screw for the electrical outlet plate. (adjacent to window). BMC 16.04.060(b)

City Hall

401 N Morton St

Bloomington, IN 47404

Hallway

The smoke detector in this room appears to be more than ten years old and the manufacturer will not guarantee it to provide adequate protection. Install a new smoke detector in an approved location. If wall mounted, it shall be located between 6 and 12 inches from the ceiling. If ceiling mounted, it shall be located at least 4 inches from the wall, IC 22-11-18-3.5

Front Bedroom (12-1 x 9-2)

Replace the missing smoke detector. IC22-11-18-3.5

Attic

Restore the integrity of the draft stop/fire separation wall in the attic. Repairs shall be made using like construction and materials. Replacement shall be done in accordance with current code requirements. BMC 16.04.020

EXTERIOR

No violations noted.

OTHER REQUIREMENTS

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.03.030(d): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner and the agent, the occupant load of the unit, the number of bedrooms, the expiration date of the permit, and any variances that have been granted for the property. BMC 16.03.030(c)

This is the end of this report.



Board of Housing Quality Appeals Staff Report: Petition for Extension of Time

Meeting Date:

18 September 2019

Petition Type:

An Extension of Time to Complete Repairs

Petition Number:

19-TV-069

Address:

2360 S Henderson St

Petitioner:

Qiuen Zhu

Inspector:

Michael Arnold

Staff Report:

03 April 2019

Cycle Scheduled by New Owner

25 April 2019 02 May 2019 Cycle Inspection Mailed Report

02 May 2019 01 July 2019

Reinspection Scheduled

13 August 2019

Reinspection Cancelled

13 August 2019

Application for Extension of Time

Several items were written on the Inspection Report. The owner is requesting additional time due to damage caused by the previous tenants.

Staff recommendation: Grant the request.

Conditions:

Complete all repairs and schedule for re-inspection no later than the

deadline stated below, or this case will be turned over to the City of Bloomington Legal Department for further action including the possibility

of fines.

Compliance Deadline: 01 December 2019

Attachments: Cycle Report, BHQA Application



EG Alli		1	W	
$A(H_0)$	· van	ģ	704	

Application for Appeal
To The
Board of Housing Quality Appeals
P.O. Box 100
Bloomington, IN 47402
812-349-3420

<u>nana(woroomingion:in.gov</u>
Property Address: 2360 S Henderson St
Petitioner's Name: Qiwn 7HU
Address: 2014 E Greenbriar Ln
City: Bloomington State: IN Zip Code: 4740
Phone Number: 626-695-7530 Email Address:
Property Owner's Name: Q; WM 2HU
Address: Same as above
City: BloommonState: JN Zip Code: 47461
Phone Number: 616-695-7530 Email Address: QINGCHAI 25@GMaiL. Con
Occupants: IV employee
The following conditions must be found in each case in order for the Board to consider the request: 1. That the exception is consistent with the intent and purpose of the housing code and promotes public health, safety and general welfare. 2. That the value of the area about the property to which the exception is to apply will not be adversely affected.
Please circle the petition type that you are requesting:
A) An extension of time to complete repairs (Petition type TV)
B) A modification or exception to the Residential Rental Unit and Lodging Establishment Inspection Program (Petition type V)
C) Relief from an administrative decision (Petition type AA)
D) Rescind a variance (Petition type RV)
REMINDER: A \$20 filling fee must be submitted with this application before the property can be placed on the meeting agenda. OFFICE USE ONLY Petition Number 19-70-69

Please provide details regarding your request below; you may attach any exhibits or additional comments as you deem necessary and pertinent to your request. Be specific as to what you are requesting, the reason or justification for your request; the amount of time needed to bring the property into compliance, and any modifications and/or alterations you are suggesting.

Dear Sir or Madam
We sincerely request an extension to complete the
repairs at 2360 S Henderson St. The reasons are listed
below = worked hard . r.
below: Worked hard to fix
the damages listed in the report However, the tenants shoughly
broken the lease and secretly moved out of the property,
teating the in made more damages, leaving the unit in a
very bad condition (pets whine and Smoke damages are everywhere)
This lead us to do more work than we thought and thus
We request an extension to have the unit repaired.
Thank You!
requesting until Dec. 1st Qiven 2HV
- All repairs and additional damages.
Signature (required): Own HV
Name (please print): Qiwen ZHU Date: 8/13/2019
Traine (protes protes)

You may attend the meeting. If you attend, please note that all petitioners presenting a matter to the Board shall be limited to no more than five minutes to present their case and arguments. Additional time can be granted if deemed appropriate by the Board. Please note that if your property is listed on the consent agenda it is more likely than not that your property will not be individually discussed during the Board's meeting.



CYCLE INSPECTION REPORT

740

Owner(s)
Qiwen Zhu
2014 E Greenbriar Ln
Bloomington, IN 47401

Prop. Location: 2360 S Henderson ST

Number of Units/Structures: 1/1

Units/Bedrooms/Max # of Occupants: Bld 1: 1/3/5

Date Inspected: 04/25/2019 Primary Heat Source: Electric

Property Zoning: RM

Number of Stories: 2

Inspector: Mike Arnold Foundation Type: Basement

Attic Access: Yes

Accessory Structure: none

Variance:

08/29/2012

This property has been granted a variance from the Indiana State Fire Safety and Building Safety Commission on August 07, 2012 for the egress requirements. Project Name: 2360 S

HENDERSON WINDOWS; Variance Number: 12-08-22.

Note:

Lower Level Center Room is not approved for sleeping.

Interior:

Lower Level:

Verify there is a smoke detector on this level and that it functions as intended.

Main Room (14-0x 11-4):

Repair the treads on the stairway to be level and secure. BMC 16.04.060(b)

Bathroom/Utility Room:

Eliminate the leak and complete the repairs to the shower. BMC 16.04.060(a)

Replace the broke floor tile. BMC 16.04.060(a) (At door)

Repair/replace the exhaust fan so it functions as intended. BMC 16.04.060(c)

Bedroom (14-0 x 10-4)

This room has a door to the exterior

Repair the door to slide easily and to latch as intended. BMC 16.04.060(b)

Properly treat and then paint the ceiling to eliminate the water stains. BMC 16.04.060(a)

Main Level:

Verify there is a smoke detector on this level and that it functions as intended.

Entry:

Repair the closet door to open/close easily. BMC 16.04.060(a) (Sticks)

Living Room (16-2 x 14-2):

No violations noted

Kitchen:

Replace the missing door knob on the pantry door. BMC 16.04.060(a)

1/2 Bathroom:

No violations noted

Upper Level:

Verify there is a smoke detector on this level and that it functions as intended.

Properly repair and surface coat the ceiling. BMC 16.04.060(f) (Above the shower)

Rear <u>Bedroom</u> (11-8 x 8-2):

Existing Egress:

Height:

23.25 inches 30.25 inches

Width:

Sill Height: Openable Area: 4.88 sq. ft.

30 inches

Note: These measurements are for reference only. There is no violation of the emergency

egress requirements.

No violations noted

Front Bedroom (14-2 x 10-0):

Existing Egress:

Height:

23.25 inches

Width:

30.25 inches

Sill Height:

30 inches

Openable Area: 4.88 sq. ft.

Note: These measurements are for reference only. There is no violation of the emergency

egress requirements.

Properly repair and surface coat the hole in the wall. BMC 16.04.060(a) (Adjacent to the closet door)

Exterior:

Provide access to the deck at reinspection

Other Requirements:

Tenants and Owners Rights and Responsibilities Summary:

A completed copy of the Tenants and Owners Rights and Responsibilities Summary must be provided to this office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied. BMC 16.03.060(c) and BMC 16.10.030(b)

Inventory Damage List:

The owner or his agent shall contact the tenant and arrange a joint inspection of the premises to occur within ten days of the tenant's occupancy of the rental unit. The owner or his agent and the tenant shall at that time jointly complete an inventory and damage list, and this shall be signed by all parties to the tenancy agreement. Duplicate copies of the inventory and damage list shall be retained by all parties and shall be deemed a part of the tenancy agreement. A completed copy of the Inventory & Damage List must be provided to the office or reviewed with the inspector within 60 days of the date of the inspection or a \$25.00 fine will be levied. BMC 16.03.050(e) and BMC 16.10.030(b)

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.03.030(d): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner or his agent and the expiration date of the permit. BMC 16.03.030(c)

This is the end of this report.



Board of Housing Quality Appeals Staff Report: Petition for Extension of Time

Meeting Date:

September 18, 2019

Petition Type:

An extension of time to complete repairs.

Petition Number:

19-TV-70

Address:

1900 S. Oakdale Dr.

Petitioner:

Douglas Cook

Inspector:

Mosier/Swinney/Wills

Staff Report:

February 25, 2019 – Conducted Cycle Inspection

June 18, 2019 – Conducted Cycle Inspection

August 14, 2019 - Received September BHQA Appeal

Petitioner is requesting an extension of time to complete the repairs in reference to drainage violation adjacent to Building H. Agent has contacted a contractor.

Staff recommendation:

Grant the request.

Conditions:

Complete all repairs and schedule for re-inspection no later than the deadline stated below, or this case will be turned over to the City of Bloomington Legal Department for further action, including, but not

limited to, the possibility of fines.

Compliance Deadline:


November 19, 2019 – For all violations.

Attachments: Cycle Report, Remaining Violations Report, Petitioner's Letter.





Application For Appeal To The Board of Housing Quality Appeals P.O. Box 100 Bloomington, IN 47402 812-349-3420 hand@bloomington.in.gov



Property Addres	s: 1900 S. Oakdal	Drive, Bloomington IN 47403	3
Petitioner's Nam	e: Douglas W. Co	ok - Agent	
Address: 2201 S. (Oakdale Drive		
City: Bloomington	7	State: Indiana	Zip Code: 47403
Phone Number:	(812) 333-4280	E-mail Address: hidden	nillspm@evergreenres.com
Owner's Name:	ASHH LLC		·
Address: 566 Wes	t Lake Street Suite	400	
City: Chicago		State: Illinois	Zip Code: 60661
Phone Number:	312-324-9400	E-mail Address:	
Occupants: 162 re	esidential units		

The following conditions must be found in each case in order for the Board to consider the request:

- 1. That the exception is consistent with the intent and purpose of the housing code and promotes public health, safety, and general welfare.
- 2. That the value of the area about the property to which the exception is to apply will not be adversely affected.

Identify the variance type that you are requesting from the following drop down menu:

Variance Type: An extension of time to complete repairs. (Petition Type: TV)

Reminder:

A \$20.00 filing fee must be submitted with the Appeal Application or the application will not be considered to be complete! A completed application has to be submitted prior to the meeting application deadline in order to be placed on that months agenda!

(Will be assigned by BHQA)

Petition Number: 19-7V-70

In the space provided below please write a brief narrative regarding your request. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting. The following information must be included dependent upon the type of variance you are requesting:

- A. An extension of time to complete repairs. (Petition type: TV)
 - 1. Specify the items that need the extension of time to complete.
 - 2. Explain why the extension is needed.
 - 3. Specify the time requested.
- B. A modification or exception to the Housing Property Maintenance Code. (Petition type: V)
 - 1. Specify the code reference number you are appealing.
 - 2. Detail why you are requesting the variance.
 - 3. Specify the modifications and or alterations you are suggesting.
- C. Relief from an administration decision. (Petition type: AA)
 - 1. Specify the decision being appealed and the relief you are seeking.
- D. Rescind a variance. (Petition type: RV)
 - 1. Detail the existing variance.
 - 2. Specify the reason the variance is no longer needed.

with them on Friday (8/9/19) but have yet to hear back from them. We are asking for an extension of time correct this issue in order to be compliant with the City inspection report.	ng ke
	to
<u> </u>	
	,

Signature (Required):	
Name (Print): Douglas W. Cook Date: 8/14/19	

Important information regarding this application format:

- 1. This form is designed to be filled out electronically, printed, then returned/submitted manually (e.g. postal mail).
- 2. This document may be saved on your computer for future use, however, any data that you have entered will not be saved.

Print Form



REMAINING VIOLATION INSPECTION REPORT

5023

Owner(s)
Ashh Llc
566 West Lake Street, Suite 400
Chicago, IL 60661

Agent

Douglas W. Cook/ Evergreen Real Estate Services 2201 S Oakdale Dr Bloomington, IN 47403

Prop. Location: 1900 S Oakdale DR Number of Units/Structures: 161/31

Units/Bedrooms/Max # of Occupants: Bld 1: Bld A: 2/4/5 2/3/5 4/2/5, Bld B: 2/4/5 2/3/5 4/2/5, Bld C: 6/3/5, Bld D: 4/2/5, Bld E: 4/3/5, Bld F: 4/3/5, Bld G: 4/2/5, Bld H: 4/2/5, Bld I: 4/2/5, Bld J: 6/3/5, Bld K: 6/3/5, Bld L: 4/3/5 4/2/5, Bld M: 4/3/5 1/4/5, Bld N: 3/3/5 2/4/5, Bld O: 4/3/5, Bld P: 6/3/5, Bld Q: 4/3/5 4/2/5, Bld R: 4/2/5, Bld S: 4/2/5, Bld T: 4/2/5, Bld U: 4/2/5, Bld V: 4/2/5, Bld W: 4/2/5, Bld X: 6/3/5, Bld Y: 5/3/5, Bld Z: 4/3/5 4/2/5, Bld AA: 4/3/5, Bld BB: 4/3/5 4/2/5, Bld

CC: 4/3/5 4/2/5, Bld DD: 4/2/5

Date Inspected: 02/25/2019 Primary Heat Source: Electric

Property Zoning: RH Number of Stories: 2 Inspector: Mosier/ Swinney/ Wills Foundation Type: Crawl Space

Attic Access: Yes

Accessory Structure: None

REINSPECTION REQUIRED

This report is your final notice from the Housing and Neighborhood Development Office that this rental property continues to be in violation of the Residential Rental Unit and Lodging Establishment Inspection Program of Bloomington.

If you have made all of the repairs on this report, contact our office immediately to schedule the required re-inspection.

Failure to make repairs or to schedule the required re-inspection will result in this matter being referred to the City Legal Department. Legal action may be initiated against you under BMC 16.10.040

It is your responsibility to contact the Housing and Neighborhood Development Office to schedule the required re-inspection. Our mailing address and telephone number are listed below.

City Hall

401 N Morton St

Bloomington, IN 47404

INTERIOR

Building B

Unit 1920

Dining Room

Secure the loose door hinges and repair the door to latch properly. BMC 16.04.060 (a)

Unit 1926

Dining Room

Repair the doorknob and deadbolt on the rear door to latch as intended. BMC 16.04.060 (a)

Building C

Unit 1950

Upper Level

Hall Bath

Secure the loose toilet to its mountings. BMC 16.04.060 (c)

Building D

Unit 1871

This unit was not inspected at the time of this inspection, as it was not accessible. (dogs were loose in apt; tenant refuses entry if not present) This unit must be inspected and brought into compliance with-in the same 60 day deadline as the remainder of this property. BMC 16.03.040

Building G

Unit 1865

Hallway

Install/replace batteries in smoke detectors so that they function as intended. IC 22-11-18-3.5

Building H

Unit 2001

Kitchen

Properly re-caulk around the countertop to eliminate water infiltration. BMC 16.04.060(a)

Building J

Unit 2008

Hall Bathroom

Properly seal the failing dry wall tape at the ceiling so that it functions as intended. BMC 16.04.060(a)

Building K

Unit 2012

Left Bedroom

The window in this room was not inspected at the time of the cycle inspection as there was no access. (blocked by bed) The window in this room must be inspected and brought into compliance with-in the same 60 day deadline as the remainder of this property. BMC 16.03.040

Building L

Unit 2034

Right Rear Bedroom

Properly repair/ replace the window locking mechanism so that it functions as intended. BMC 16.04.060(b)

Building O

Unit 2062

NW Bedroom (Master)

Repair the smoke detector in this room to be interconnected. IC 22-11-18-3.5

Building P

Living Room

Replace the deteriorated rubber strip on the threshold, so that the threshold is weather tight. BMC 16.04.060 (a)

Building R

Unit 2100

L Bedroom

Secure the loose receptacle. (Below window) BMC 16.04.060 (b)

Building Y

Unit 2222

Living Room

Repair the smoke detector in this room to be interconnected. IC 22-11-18-3.5

Kitchen

Repair/replace the damaged laundry closet door. BMC 16.04.060(a)

Unit 2224

Upper Level

Front Right Bedroom

Replace the broken window pane. BMC 16.04.060(a)

Building Z

Upper Level

Hall Bath

Secure the loose toilet to its mountings. BMC 16.04.060 (c)

Unit 2204

NE Bedroom

Install/replace batteries in smoke detectors so that they function as intended. IC 22-11-18-3.5

Building AA

Unit 2294

Left Back Bedroom

Repair the smoke detector in this room to be interconnected. IC 22-11-18-3.5

Unit 2296

Front Right Bedroom

Repair or replace existing smoke detector in a manner so that it functions as intended. IC 22-11-18-3.5

Building CC

Unit 2268

Right Bedroom

This room was not accessible at the time of this inspection. (tenant refuses entry) This room must be brought into compliance with-in the same 60 day deadline as the remainder of this property. BMC 16.03.040

Unit 2262

Kitchen

Repair the faucet sprayer on the sink to function as intended by the manufacturer, or remove and properly terminate the line for the sprayer. BMC 16.04.060(c)

Front Left Bedroom

Repair the window to remain fully open using hardware that is part of the window. BMC 16.04.060(b)

EXTERIOR

Building D

Trim all tree branches away from the siding and roofline to maintain a 3' clearance. BMC 16.04.040(e)

Building G

Properly repair or replace damaged or deteriorated siding on the front of the building next to the door for unit 1865 in a manner that leaves the structure weather tight. This is to be done in a workmanlike manner and includes but is not limited to all damaged or deteriorating siding and structural members. BMC 16.04.050(a)

Trim all tree branches away from the siding and roofline to maintain a 3' clearance. BMC 16.04.040(e)

Building H

Regrade Ground to direct water away from the back of the building and crawlspace entrance. BMC 16.04.050(a)

Building I

Properly replace missing siding on the North gable in a manner that leaves the structure weather tight. This is to be done in a workmanlike manner and includes but is not limited to all missing, damaged, or deteriorating siding and structural members. BMC 16.04.050(a)

Building K

Secure the loose siding on north end of structure at soffit and bottom of wall. BMC 16.04.050(a)

Building P

Properly repair or replace damaged or deteriorated siding on the West wall of storage room for unit 2075 in a manner that leaves the structure weather tight. This is to be done in a workmanlike manner and includes but is not limited to all damaged or deteriorating siding and structural members. BMC 16.04.050(a)

Building Q

Properly repair or replace damaged or deteriorated siding corner on the front of the building next to unit 2085 in a manner that leaves the structure weather tight and excludes the entrance of rodents. This is to be done in a workmanlike manner and includes but is not limited to all damaged or deteriorating siding and structural members. BMC 16.04.050(a)

Building R

Secure the loose siding on band, east side of structure. BMC 16.04.050(a)

Building W

Remove the mold on the north side of structure. BMC 16.04.050(f)

Building X

Secure the loose siding on west end of structure. BMC 16.04.050(a)

Building Y

Secure the loose siding on east end of structure. BMC 16.04.050(a)

Paint the door trim on the front facing exterior doors. BMC 16.04.050(a)

Building Z

Paint the door trim on the front facing exterior doors. BMC 16.04.050(a)

OTHER REQUIREMENTS

When issued, a copy of the new Rental Occupancy Permit shall be posted as required by BMC 16.03.030(d): All rental units shall be required to have a current occupancy permit displayed in an accessible location inside the unit. The permit shall contain the name of the owner and the agent, the occupant load of the unit, the number of bedrooms, the expiration date of the permit, and any variances that have been granted for the property. BMC 16.03.030(c)

This is the end of this report.



Board of Housing Quality Appeals Staff Report: Petition for Extension of Time

Meeting Date:

September 18, 2019

Petition Type:

An extension of time to complete repairs

Petition Number:

19-AA-71

Address:

213 S Jefferson St

Petitioner:

Nicholas Weybright

Inspector:

Michael Arnold/John Hewett

Staff Report:

16 April 2019 Scheduled Complaint Inspection
18 April 2019 Complaint Inspection
29 April 2019 Sent Complaint Inspection Report
13 May 2019 Received BHQA Application
19 June 2019 BHQA Meeting Cancelled

19 June 2019 BHQA 17 July 2019 BHQA

BHQA Granted extension until August 17.

16 August 2019

Received AA Appeal from the owner.

The complaint included concerns about the structural stability of the basement foundation walls. There is some dislocation of the masonry block which may be a structural concern. The report requested repairs or documentation from a design professional regarding the deterioration. The petitioner has requested relief from the requirement to make structural repairs, and wants to address water issues as an alternative.

Staff recommendation:

Deny the Appeal

Conditions:

Complete all repairs and schedule for re-inspection, or provide signed and stamped documentation from a Structural Engineer no later than the deadline stated below, or this case will be turned over to the City of Bloomington Legal Department for further action

including the possibility of fines.


Compliance Deadline:

October 17, 2019

Attachments:

Application, Complaint report, Picture

4







Application/For Appeal
To The
Board of Housing Quality Appeals
P.O. Box 100
Bloomington, IN 47402
812-349-3420
hand@bloomington.in.gov

Property Address: 213 S Jefferso	on St., Bloomington, IN 474	08		
Petitioner's Name: Nicholas Wey	/bright			
Address: 6925 E. 96th Street, Suit	te 255			
City: Indianapolis	State: Indiana	Zip Code: 46250		
Phone Number: 3175387000	E-mail Address: nick@weybright.com			
Owner's Name: Nicholas Weybrig	ght			
Address: 6925 E. 96th Street, Suit	e 255			
City: Indianapolis	State: Indiana	Zip Code: 46250		
Phone Number: 3175387000	E-mail Address: nick@v	weybrìght.com		
Leah Baumann, Catherin	ne DeBruyn & Katelyn Lenahar)		
 That the exception is consistent health, safety, and general welfa 	with the intent and purpore.	der for the Board to consider the request: se of the housing code and promotes public e exception is to apply will not be adversely		
Identify the variance type that y	ou are requesting from	the following drop down menu:		
Variance Type: Relief from an add	ministrative decision. (Petitio	on Type: AA)		
Reminder: A \$20.00 filing fee must be submit Application or the application will complete! A completed applicatio prior to the meeting application de	not be considered to be n has to be submitted	(Will be assigned by BHQA)		
placed on that months agendal		Petition Number: 19-41-71		

In the space provided below please write a brief narrative regarding your request. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting. The following information must be included dependent upon the type of variance you are requesting:

- A. An extension of time to complete repairs. (Petition type: TV)
 - 1. Specify the items that need the extension of time to complete.
 - 2. Explain why the extension is needed.
 - 3. Specify the time requested.
- B. A modification or exception to the Housing Property Maintenance Code. (Petition type: V)
 - 1. Specify the code reference number you are appealing.
 - 2. Detail why you are requesting the variance.
 - 3. Specify the modifications and or alterations you are suggesting.
- C. Relief from an administration decision. (Petition type: AA)
 - 1. Specify the decision being appealed and the relief you are seeking.

The second secon

- D. Rescind a variance. (Petition type: RV)
 - 1. Detail the existing variance.
 - 2. Specify the reason the variance is no longer needed.

-	Α.
nk you for your consideration. I look forward to speaking with you,	
will install downspout extensions that will extend water out 15 feet or more past the foundate: will install an auto drip dehumidifier in the unfinished basement. will install a floor drain at the lowest spot of the basement near the laundry. will be sure that all debris is removed from the gutters and maintain clean gutters.	

Important information regarding this application format:

- 1. This form is designed to be filled out electronically, printed, then returned/submitted manually (e.g. postal mail).
- 2. This document may be saved on your computer for future use, however, any data that you have entered will not be saved.

Print Form



APR 2 9 2019

57ub Llc Po Box 6277 Fishers, IN 46038

RE:NOTICE OF COMPLAINT INSPECTION

Dear 57ub Llc

On 04/18/2019 a complaint inspection was performed at 213 S Jefferson ST. During the inspection violations of the Residential Rental Unit and Lodging Establishment Inspection Program were found.

Please correct the violations cited on the enclosed inspection report within fourteen days (14) and call this office no later than MAY 1 3 2019, to schedule the required re-inspection. Our mailing address and telephone number are listed below.

This directive is issued in accordance with Sections BMC 16.03.040 (c) and 16.10.040 (a) of the Residential Rental Unit and Lodging Establishment Inspection Program of Bloomington. You have the right to appeal to the Board of Housing Quality Appeals. If you need more than fourteen (14) days to correct the violations, or if you want to appeal any violation, an appeal form can be found at www.bloomington.in.gov/hand. If you do not have access to the internet, you may contact HAND at 812-349-3420 and a form will be provided.

Please remember, it is your responsibility to contact the Housing and Neighborhood Development Department to schedule the required re-inspection.

If you have any questions regarding the permit process, please call weekdays between 8:00 a.m. and 5:00 p.m., at (812) 349-3420.

Sincerely,

Housing & Neighborhood Development

Encl:Inspection Report,

Xc:Tempo Properties Inc.: P.O. Box 5727, Bloomington, IN 47407





City Of Bloomington Housing and Neighborhood Development COMPLAINT INSPECTION REPORT

1079

Owner(s) 57ub Llc Po Box 6277 Fishers, IN 46038

Agent

Tempo Properties Inc. P.O. Box 5727 Bloomington, IN 47407

Prop. Location: 213 S Jefferson ST Number of Units/Structures: 1/1

Units/Bedrooms/Max # of Occupants: Bld 1: 1/3/4

Date Inspected: 04/18/2019 Primary Heat Source: Gas Property Zoning: RC Number of Stories: 2

Inspector: Mike Arnold Foundation Type: Basement

Attic Access: No

Accessory Structure: none

The following items are the result of a complaint inspection conducted on 04/18/2019. It is your responsibility to repair these items and to schedule a re-inspection within fourteen (14) days of the mailing of this report. Failure to comply with this inspection report will result in this matter being referred to the City of Bloomington Legal Department. Failure to comply with this complaint inspection report may result in fines. If you have questions regarding this report, please contact this office at 349-3420.

Interior:

Repair the plumbing/drain lines to eliminate back up into the bathroom and kitchen sinks. BMC 16.04.060(c)

Basement:

Repair the walls and floor as necessary to eliminate water infiltration. BMC 16.04.060(a)


Repair the foundation walls to be structurally sound or provide documentation from a design professional stating the walls are structurally sound. BMC 16.01.060(f)


City Hall


<u>Upper Level:</u> Repair/replace the window sashes that have fogged or have moisture between the panes of glass. BMC 16.04.060(a)

Exterior:

Eliminate the downed trees, wood and brush from the property. BMC 16.04.050(a)(d)









Board of Housing Quality Appeals Staff Report: Petition for Relief from an Administrative Decision

Meeting Date:

September 18, 2019

Petition Type:

Relief from an administrative decision

Variance Request:

Relief from the requirement to register and inspect.

Petition Number:

19-AA-72

Address:

3336 S Oaklawn Circle

Petitioner:

Yiping Lin

Inspector:

John Hewett

Staff Report: August 6, 2019

Notice to register and schedule inspection is sent to owner.

August 15, 2019

Owner called to say his daughter lives here. Advised him to

appeal for Variance.

August 15, 2019

Received appeal and fee from the owner.

This house is occupied by the owner's daughter. The owner is asking for relief from the requirements of Title 16.

Staff recommendation: Grant the relief from administrative decision.

Conditions: This unit will be granted relief from the requirements of Title 16 for as long as the current owner and tenant are still un-changed from the current status. The property status will be checked yearly to verify no changes have been made. If this status changes, the requirements of Title 16 may be re-instated.

Compliance Deadline: none Attachments: Appeal form





Application for Appeal To The

Board of Housing Quality Appeals
P.O. Box 100

Bloomington, IN 47402
812-349-3420

, <u>hand@bloomington.in.gov</u>
Property Address: 3336 S oaklawn Civ.
Petitioner's Name: Yiping ('M')
Address: 3336 S oaklann Civ
city: Bloomington. State: IN. zip Code: 4740/:
Phone Number: 678-632-199 7 Email Address: 2543 R 903/5@gmail. (om
Property Owner's Name: Yip'ing L'M.
Address: 386 8 oaklam Cts 25/0 B clay Ct.
city: Bloomington state: IN: zip code: 4/401.
Phone Number: 678-632-199 Email Address: R 90315 agmont. Com.
Occupants: Chet.
 The following conditions must be found in each case in order for the Board to consider the request: That the exception is consistent with the intent and purpose of the housing code and promotes public health, safety and general welfare. That the value of the area about the property to which the exception is to apply will not be adversely affected.
Please circle the petition type that you are requesting:
A) An extension of time to complete repairs (Petition type TV)
A modification or exception to the Residential Rental Unit and Lodging Establishment Inspection Program (Petition type V)
C) Relief from an administrative decision (Petition type AA)
D) Rescind a variance (Petition type RV)
REMINDER: A \$20 filing fee must be submitted with this application before the property can be placed on the meeting agenda. OFFICE USE ONLY Petition Number 19-AA-72.

as you deem nece reason or justificat	ion for your reque	est; the amount o	of time needed	to bring the p	roperty into co	mpliance,
and any modificati	ons and/or alterat	ions you are sug	gesting.	doing hAPA	/	
his h	ome is	live. Di)	1 may react	<u>,</u>	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
There	is no	payment	11	Detween	u_{S} .	
Tam	Supporting	her of	or follo	wing one.	y-ear	by
not co	llect feel	rti.			·	·
	, ,					
I would	1 life :	this prop	perty to	be e	Xempt	from
	proporty	Require	ment.			
,		/			•	
		,		•		
-					•	
			_		•	
	•	•			,	•
		•		•		
	· ·	-			,	•
		٠.	•	•	•	
, Signature (required	n: YI PING	LIN				
	•	Lin.			.8-15	19
Name (please print	: Tibind	CIVI.		Date: _	<u>د</u> ا <i>ن</i>	1
•	•					

Please provide details regarding your request below; you may attach any exhibits or additional comments

You may attend the meeting. If you attend, please note that all petitioners presenting a matter to the Board shall be limited to no more than five minutes to present their case and arguments. Additional time can be granted if deemed appropriate by the Board. Please note that if your property is listed on the consent agenda it is more likely than not that your property will not be individually discussed during the Board's meeting.



Meeting Date:

September 18, 2019

Petition Type:

Relief from an administrative decision

Variance Request:

Relief from the requirement to remove upholstered furniture from a porch.

Petition Number:

19-AA-74

Address:

803 N Lincoln St.

Petitioner:

Isaac Peterson

Inspector:

Michael Arnold/ John Hewett

Staff Report:

August 9, 2019

Received Rental Complaint concerning couch on this porch.

August 15, 2019

Tenant Violation Report issued.

August 21, 2019

Received appeal and fee.

The tenant at 803 N Lincoln Street has appealed for relief from the requirement to remove the upholstered furniture from the porch. He states this furniture is designed for outdoor use.

Staff recommendation: Deny the relief from administrative decision.

Conditions: The furniture shall be removed from the porch and placed indoors.

Compliance Deadline: September 25, 2019

Attachments: Complaint email and form, Tenant Violation Report, Appeal form, Photos



City Hall

In the space provided below please write a brief narrative regarding your request. Be specific as to what you are requesting, the reason(s) or justification(s) for your request, the amount of time needed to bring the property into compliance, as well as any modifications and/or alterations you are suggesting. The following information must be included dependent upon the type of variance you are requesting:

- A. An extension of time to complete repairs. (Petition type: TV)
 - 1. Specify the items that need the extension of time to complete.
 - 2. Explain why the extension is needed.
 - 3. Specify the time requested.
- B. A modification or exception to the Housing Property Maintenance Code. (Petition type: V)
 - 1. Specify the code reference number you are appealing.
 - 2. Detail why you are requesting the variance.
 - 3. Specify the modifications and or alterations you are suggesting.
- C. Relief from an administration decision. (Petition type: AA)
 - 1. Specify the decision being appealed and the relief you are seeking.
- D. Rescind a variance. (Petition type: RV)
 - 1. Detail the existing variance.
 - 2. Specify the reason the variance is no longer needed.

The administration decision made stated that we are in violation of BMC 16.04.040(f) which says: "Furniture not generally intended to be used for outdoor purposes (typically upholstered furniture), shall not be permitted to be stored on the exterior premises of residential rental units, this includes both screened-in porches and non-screened porches." Specifically the issue was with the outdoor seating that we have on our front porch.

In accordance with section f, the seating items shall not "GENERALLY (be) intended to be used for outdoor purposes." Our seating items were labeled as outdoor seating when we purchased them and are designed for that intent. Additionally, our items are not upholstered, they are made from a weather-resistant leather. Therefore, we believe our porch furniture is not in violation of any BMC line items and we request a petition of this decision with the ultimate goal of leavaing the furniture on our porch.

1 Sans Sales		
Signature (Required):		
Name (Print): Isaac Peterson	Date:	58/21/2019

Important information regarding this application format:

- 1. This form is designed to be filled out electronically, printed, then returned/submitted manually (e.g. postal mail).
- 2. This document may be saved on your computer for future use, however, any data that you have entered will not be saved.

Print Form



AUG 1 5 2019

Tariq Khan 1201 W. Allen Street # 19 Bloomington, IN 47403

RE:NOTICE OF TENANT VIOLATION INSPECTION

Dear Resident(s)

On 08/12/2019, a complaint inspection was performed at 803 N Lincoln ST. During the inspection violations of the Bloomington Housing Code were found. Enclosed is the inspection report which cites violations that are the responsibility of the resident(s) to correct. Please correct the violations within days and contact this office no later than AUG 3 0 2019 to schedule the required re-inspection. Our mailing address and telephone number are listed below.
This directive is issued in accordance with BMC 16.10.020(a) and 16.10.040(a) of the Residential Rental Unit and Lodging Establishment Inspection Program. You have the right to appeal to the Board of Housing Quality Appeals. If you need more than days to correct the violations, or if you want to appeal any violation, an appeal form can be found at www.bloomington.in.gov/hand. If you do not have access to the internet, you may contact HAND at 812-349-3420 and a form will be provided.
Please remember, it is your responsibility to contact the Housing and Neighborhood Development Office to schedule the required re-inspection.
If you have any questions regarding the permit process, please call weekdays between 8:00 a.m. and 5:00 p.m., at (812) 349-3420.
Sincerely,
Housing & Neighborhood Development Encl:Inspection Report,



TENANT VIOLATION INSPECTION REPORT

1237

Owner(s)

Tenants

Tariq Khan

Tenants

1201 W. Allen Street # 19

803 N Lincoln St

Bloomington, IN 47403

Bloomington IN 47408

Prop. Location: 803 N Lincoln ST Number of Units/Structures: 1/1

Units/Bedrooms/Max # of Occupants: Bld 1: 1/5/5

Date Inspected: 08/12/2019 Primary Heat Source: Gas Property Zoning: RC

Attic Access: No

Number of Stories: 2

Accessory Structure: none

Foundation Type: Basement

Inspector: Mike Arnold

A complaint was received that is the responsibility of the tenants to correct. The violations must be corrected and reinspected for compliance with the Residential Rental Unit and Lodging Establishment Inspection Program within 14 days of the date on which this notice was mailed. It is the responsibility of the tenant to contact this office to schedule the required re-inspection at 349-3420. Any questions can be addressed to the inspector at 349-3420.

Failure to comply with the requirements of this notice will result in this matter being forwarded to the City's Legal Department for legal action and fines under the provisions of Title 16 of the Bloomington Municipal Code.

Exterior:

Remove the couch and other upholstered furniture from the front porch of the house. BMC 16.04.040(f)

This is the end of this report.



COMMENTS:

CITY OF BLOOMINGTON RENTAL COMPLAINT FORM

HOUSING & NEIGHBORHOOD DEVELOPMENT P.O. BOX 100 BLOOMINGTON, IN 47401 PHONE: (812) 349-3420 FAX: (812) 349-3582 EMAIL: hand@bloomington.in.gov



ADDRESS OR LOCATION OF THE COMPLAIN		>5.5.5000000000000000000000000000000000
COMPLAINANT INFORMATION		
NAME: James Ford		
STREET ADDRESS: PO Box 3268		
_{CITY:} Bloomington	STATE: IN	_{ZIP:} 47402
PHONE:		
NATURE OF THE PROBLEM Couches on porch		
·		
HOW LONG HAS THE PROBLEM EXISTED: one year		
WHEN DID YOU NOTIFY THE OWNER/AGENT:		
HOW DID YOU NOTIFY THE OWNER/AGENT: \Box	IN PERSON 🗆 IN WRIT	TING DBY PHONE
COMPLAINANT SIGNATURE:		
OFFICE USE ONLY		V
OWNER'S NAME:		
ADDRESS:		
NEIGHBORHOOD COMPLIANCE OFFICER:		
HOUSING CODE FILE: ☐ YES ☐ NO CITY LIMITS: ☐ YES ☐ NO 2 MILE FRINGE: [□ YES □ NO	
COMPLAINT RECEIVED BY:	DATE:	TIME:



Daniel Bixler < bixlerd@bloomington.in.gov>

Fwd: couches on porches in Highpoint Neighborhood

1 message

Eric Sader <sadere@bloomington.in.gov>
To: Daniel Bixler
bixlerd@bloomington.in.gov>

Thu, Aug 1, 2019 at 10:10 AM



Eric A. Sader, JD, MSW, LSW
Assistant Director, Housing and Neighborhood Development
City of Bloomington, Indiana.
401 N. Morton Street, Suite 130, Bloomington, IN 47404
sader @bloomington.in.gov, 812-349-3420 x3577, 812-349-3582 (tex)

----- Forwarded message ------From: Ford, James <jbford@indiana.edu>

Date: Thu, Aug 1, 2019 at 10:06 AM

Subject: couches on porches in Highpoint Neighborhood To: hand@bloomington.in.gov <hand@bloomington.in.gov>

Dear HAND,

Attached are complaint forms for two addresses (803 and 810 N. Lincoln) where tenants have placed couches on porches.

Side comment: I think it would be helpful if landlords were asked to inform their tenants of the various City regulations that are regularly violated. Specifically:

- 1. Noise
- 2. Trash
- 3. Couches on porches
- 4. Bonfires
- 5. Trespassing

Perhaps this could be done whenever a landlord renews a rental permit. If the City required all leases contain a simple paragraph outlining some basic guidelines, one that included the URLs to the relevant online Code articles, the violation rate might drop.

Thank you,

James Ford

2 attachments

- rental_complaint_form-810-Lincoln.pdf 87K
- rental_complaint_form-803-Lincoln.pdf 82K